

ANNUAL SURVEYS.

33857
Recd 2.1.77

No. in Reg. Book. on the **No.** 204 Survey held at London Date, first Survey 2nd Dec. Last Survey 20th Dec. 18 76
 Tonnage 1283 Built at London Master Whitcombe
 By whom built Green Owners R & H Green
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 3477 Port of London Classed 14 Years assigned. 14 Character in Register Book. A.1.
 Present Condition of the Decks Good Treenails Good Cont. Low. 74.9.76 6-73.
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling Ballast in hold
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. Y.M. When put on _____
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom sighted, yellow metal sheathing patched, and the topsides recaulked.


This Vessel is now in good and efficient condition and eligible to remain as classed.

Committee's Minute 5th January 18 77 Thos. W. Blasell
 Character assigned Cou 9 A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in Reg. Book. on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____ Years assigned. _____ Character in Register Book. _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Caulking of Bottom, Deck, & Waterways _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____



© 2021

Lloyd's Register Foundation

10610458