

ANNUAL SURVEYS.

35915

Recd 31.1.77

No. in Reg. Book. **521** No. **34815** Survey held at **LONDON** Date, first Survey **8 Feb / 76** Last Survey **22 Dec** 18 **76**
 on the **Dunphail Castle** Master **Hilder**
 Tonnage **720** Built at **Sunderland** When built **1861** **9 mo**
 By whom built **Laing** Owners **J. Allan &**
 Port belonging to **London** Destined Voyage _____
 If Surveyed Afloat or in Dry Dock **At letchers dock**

Last Survey, No. **34815** Port of **London** Classed **14** Years assigned **41** Character in Register Book **A1 7.75**
Sub 76-9 1/2
True

Present Condition of the Decks _____ Waterways _____ Comings _____ Upper Deck Beams & Fastenings _____ Lower Deck Beams & Fastenings _____ Planksheers _____ Sheerstrakes _____ Topsides _____ Wales _____ Plank (Bottom) and Counter _____ Engine Room Skylights _____ General Observations, Opinion as to Class, &c. _____	Treenails _____ Breasthooks and Stemson _____ Transoms, Pointers, and Crutches _____ Timbers of the Frame at the Openings _____ Ditto ditto at other places _____ Keelsons _____ Clamps and Shelves _____ Ceiling _____ Rudder _____ Copper or Y.M. _____ When put on _____ Caulking of Bottom, Deck, & Waterways _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers _____	Windlass and Capstan _____ Pumps _____ Boats _____ Masts, Yards, &c. _____ Condition, how ascertained _____ Sails _____ Anchors, No. of _____ Cables _____ Hawasers and Warps _____ Standing and Running Rigging _____ Cargo and Main Hatchways _____ Hatches _____
--	---	--

This vessel appears in good condition and eligible to remain as classed.

Committee's Minute **6th February 1877** **J. Congdon**
 Character assigned **Class 14** Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in Reg. Book. on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____ Years assigned _____ Character in Register Book _____

Present Condition of the Decks _____ Waterways _____ Comings _____ Upper Deck Beams & Fastenings _____ Lower Deck Beams & Fastenings _____ Planksheers _____ Sheerstrakes _____ Topsides _____ Wales _____ Plank (Bottom) and Counter _____ Engine Room Skylights _____ General Observations, Opinion as to Class, &c. _____	Treenails _____ Breasthooks and Stemson _____ Transoms, Pointers, and Crutches _____ Timbers of the Frame at the Openings _____ Ditto ditto at other places _____ Keelsons _____ Clamps and Shelves _____ Ceiling _____ Rudder _____ Copper or Y.M. _____ When put on _____ Caulking of Bottom, Deck, & Waterways _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____	Windlass and Capstan _____ Pumps _____ Boats _____ Masts, Yards, &c. _____ Condition, how ascertained _____ Sails _____ Anchors, No. of _____ Cables _____ Hawasers and Warps _____ Standing and Running Rigging _____ Cargo and Main Hatchways _____ Hatches _____
--	--	--

Committee's Minute _____ 18 _____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____



LON 661-0184

Dunphail Castle



© 2021

Lloyd's Register
Foundation