

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** 1287 on the S Asterope Survey held at London Date, first Survey July 7 Last Survey July 29 1876

Master Hamer
 Tonnage under Tonnage Deck 602
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage
 Crew Space, by Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St' mer, cut on Bm.
 Built at Aberdeen When built 1857
 Owners J Rhoads Port belonging to London
 Residence
 By whom built Hall Destined Voyage
 If Surveyed Afloat or in Dry Dock Dry Dock

Length of Poop 37 ft. Ditto, Forecastle 10 ft. Ditto, Raised Quarter Deck 10 ft. Years assigned. 14 Character in Register Book.

Last Survey, No. 34778 Port London Classed 14A 6.75
Cons. Lm. 73-29

REPAIRS, OR EXAMINATION AS PER RULE

*At the present time the Yellow Metal
 stripped off Caulken from Keel to Top of
 Wales & Yellow Metalled on felt to load line
 New Prosprit*

Cause of Repairs to be clearly stated.

Present Condition of the					
Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Pumps	
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Boats	
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the openings	<u>"</u>	Masts, Yards, &c.	<u>Good V.</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto Ditto at other places	<u>"</u>	Condition, how ascertained	<u>Sufficient</u>
Planksheers	<u>"</u>	Keelsons	<u>"</u>	Sails	<u>when</u>
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>	Anchors No. of <u>3</u>	<u>They</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>	Cables	<u>could</u>
Wales	<u>"</u>	Rudder	<u>"</u>	Hawsers and Warps	<u>be seen</u>
Plank (Bottom) and Counter	<u>"</u>	Copper of Metal When put on <u>new</u>		Standing & Running Rigging	
Engine Room Skylights	<u>"</u>	in felt Caulking of			
Coal Bunker, Openings, Lids, &c.	<u>"</u>	Bottom, Deck, & Waterways	<u>Good</u>		
General Observations, Opinion as to Class, &c.		Scuppers	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
				Hatches	<u>Good</u>

*She is now in an efficient state
 of repair & entitled to remain as classed*

Senhouse Martin

The Amount of Entry Fee ... £ ...
 Special ... £ ...
 Certificate (if required) ... £ ...
 (Travelling Expenses, if any, £ ...)
 Committee's Minute 13th February 1877
 Character assigned Good

Surveyor to Lloyd's Register of British and Foreign Shipping.



CON662-0007