

# ANNUAL SURVEYS.

33,948

No. in Reg. Book. **80** No. **10914** Survey held at **London** Date, first Survey **22<sup>nd</sup> Jan'y** Last Survey **23<sup>rd</sup> Jan'y** Rec'd 15.2.77 1877  
 on the Ship **"V.L. Lawrence"** Master **C. Johnson**  
 Tonnage **10914** Built at **Newcastle** When built **1861-3 mo**  
 By whom built **Smith** Owners **J. Southern & J. Luckley.**  
 Port belonging to **Newcastle** Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock **Greens Lower dry dock.**

Last Survey, No. **13044** Port of **Newcastle** Classed **15** Years assigned. **A.1.** Character in Register Book. **11-75**  
 Present Condition of the Decks **Good** Treenails **Good** Cont. Shl. **75. 5 yrs**  
 Waterways **---** Breasthooks and Stemson **---** Windlass and Capstan **Good**  
 Comings **---** Transoms, Pointers, and Crutches **---** Pumps **---**  
 Upper Deck Beams & Fastenings **---** Timbers of the Frame at the Openings **---** Boats **---**  
 Lower Deck Beams & Fastenings **---** Ditto ditto at other places **---** Masts, Yards, &c. **---**  
 Planksheers **---** Keelsons **Ballast in hold** Condition, how ascertained **From Deck**  
 Sheerstrakes **---** Clamps and Shelves **---** Sails **Good**  
 Topsides **---** Ceiling **---** Anchors, No. of **3 Bts 18<sup>th</sup> 21<sup>st</sup> age**  
 Wales **---** Rudder **---** Cables **Good**  
 Plank (Bottom) and Counter **---** Copper or Y.M. **on felt** When put on **1875** Hawser and Warps **and**  
 Engine Room Skylights **---** Caulking of Bottom, Deck, & Waterways **Good** Standing and Running Rigging **Sufficient**  
 Coal Bunker, Openings, Lids, &c. **---** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c. **Bottom and keel sighted, yellow metal sheathing patched, and the topsides recaulked.**

*This Vessel is now in good and efficient condition and eligible to remain as Classed.*

Committee's Minute **20<sup>th</sup> February 1877** Character assigned **Class 5A** **Thos Wm Blaydel.**  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

No. \_\_\_\_\_ Survey held at **London** Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18 \_\_\_\_\_  
 No. in Reg. Book. on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_ Years assigned. \_\_\_\_\_ Character in Register Book. \_\_\_\_\_  
 Present Condition of the Decks \_\_\_\_\_ Treenails \_\_\_\_\_  
 Waterways \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_ Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_