

REPORT of SURVEY for REPAIRS, &c.

36098A

No. in Reg. Book. **No.** Survey held at London Date, first Survey 11th Jan^y Last Survey 28th Jan^y 1876
441 on the Ship "Alexandrina" Master J. Sangster
 Official Number 8855
 TONNAGE under Tonnage Deck
 Ditto of Spar Deck, or Avoning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as S^r mer, cut on Bm.
 Built at Glasgow When built 1864
 Owners J. Brodie Port belonging to London
 Residence
 By whom built Smith Destined Voyage
 If Surveyed Afloat or in Dry Dock Princes by Lock & Afloat

Length of Poop 48.6 ft. Ditto, Forecastle 31 - ft. Ditto, Raised Quarter Deck
 Last Survey, No. 2850 Port Plymouth Cont. Low 73 Classified 9 Years assigned 6 Character in Register Book A.1.
8-73

REPAIRS, OR EXAMINATION AS PER RULE Remetalling &c.

Yellow metal sheathing stripped off bottom and keel sighted, main piece of Rudder strengthened with two Iron hoops at head, caulked from keel to metal line, and the bottom sheathed with yellow metal over felt.

sent Condition of the	<u>good</u>	Treenails	<u>good</u>	Windlass and Capstan	<u>good</u>
erways	<u>br</u>	Breasthooks and Stemson	<u>br</u>	Pumps	<u>br</u>
ings	<u>br</u>	Transoms, Pointers, and Crutches	<u>br</u>	Boats	<u>br</u>
per Deck Beams & Fastenings	<u>br</u>	Timbers of the Frame at the openings	<u>br</u>	Masts, Yards, &c.	<u>br</u>
Lower Deck Beams & Fastenings	<u>br</u>	Ditto Ditto at other places	<u>br</u>	Condition, how ascertained	<u>from deck</u>
Planksheers	<u>br</u>	Keelsons	<u>br</u>	Sails	<u>good</u>
Sheerstrakes	<u>br</u>	Clamps and Shelves	<u>br</u>	Anchors No. of <u>3 1/2</u> 18 th 2 1/2 age	
Topsides	<u>br</u>	Ceiling	<u>br</u>	Cables	<u>good</u>
Wales	<u>br</u>	Rudder	<u>br</u>	Hawsers and Warps	<u>and</u>
Plank (Bottom) and Counter	<u>br</u>	Copper <u>Y.M. & L</u> When put on <u>now</u>		Standing & Running Rigging	<u>sufficient</u>
Engine Room Skylights	<u>—</u>	Caulking of		Cargo and Main Hatchways	<u>good</u>
Coal Bunker, Openings, Lids, &c.	<u>—</u>	Bottom, Deck, & Waterways	<u>good</u>	Hatches	<u>good</u>

General Observations, Opinion as to Class, &c. This Vessel is now in good and efficient condition and eligible to remain as Classed; by Cont^d A.1. for 6 yrs

The Amount of Entry Fee ... £ : : received by me, }
 Special ... £ 2 : 2 : 23 Apr 1876
 Certificate (if required) ... £ : 5 -
 (Travelling Expenses, if any, £)
 Committee's Minute on the 19th May 1876
 Character assigned Cont^d A.1.

Thos Wm Blapell.
 Surveyor to Lloyd's Register of British and Foreign Shipping.



LON 662-0094

The Surveyors are requested not to write on or below the space for Committee's Minute.

[3,000—1/11/75.]