

# REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** Survey held at Sunderland Date, first Survey April 11 Last Survey April 25 1877

404 on the BK Alchymist Master Reid 28.4.77

TONNAGE under Tonnage Deck 508 Built at Sunderland When built 1853  
 Ditto of Spar Deck, or Awning Deck  
 Ditto of Poop  
 Ditto of Raised Qr. Dk.  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage 540 Owners R Jolly & Co Port belonging to Sunderland  
 Crew Space, as per Rule  
 Register Tonnage, cut on Beam 540 Residence  
 Engine Room By whom built Thompson Destined Voyage  
 Reg. Tons as St' mer, cut on Bm. If Surveyed Afloat or in Dry Dock In the port cargo in

Length of Poop 23 ft. Ditto, Forecastle 40 ft. Ditto, Raised Quarter Deck 40 ft. Years assigned. Character in Register Book.

Last Survey, No. 35460 Port London Classed 11/11/76 576

REPAIRS, OR EXAMINATION AS PER RULE

at the present time the vessel placed  
by dark and the yellow metal patched.  
New bowsprit of Patch Pine.

The owner was informed that her present  
clasp expires at the end of this year

Present Condition of the					
Decks	<u>good</u>	Treenails	<u>good</u>	Windlass and Capstan	
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Pumps	
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Boats	
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the openings	<u>"</u>	Masts, Yards, &c.	<u>good</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto Ditto at other places	<u>"</u>	Condition, how ascertained	<u>sufficient</u>
Planksheers	<u>"</u>	Keelsons	<u>"</u>	Sails	<u>where</u>
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>	Anchors No. of <u>Brass</u> <u>old</u> <u>red</u> <u>red</u>	<u>they</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>	Cables	<u>could</u>
Wales	<u>"</u>	Rudder	<u>"</u>	Hawsers and Warps	<u>he</u>
Plank (Bottom) and Counter	<u>"</u>	Copper <u>of Metal</u> When put on <u>1874</u>	<u>good</u>	Standing & Running Rigging	<u>seen</u>
Engine Room Skylights	<u>"</u>	Caulking of <u>Patched</u> <u>new</u>	<u>good</u>	Cargo and Main Hatchways	<u>good</u>
Coal Bunker, Openings, Lids, &c.	<u>"</u>	Bottom, Deck, & Waterways	<u>good</u>	Hatches	<u>good</u>
Scuppers	<u>good</u>				

General Observations, Opinion as to Class, &c.

She is now in an efficient state of  
repair and entitled to remain as Clasp

Senhouse W. M. T. M. A.  
Shearle

The Amount of Entry Fee ... £ ... received by me, 1877  
18/4/77 Special ... £ ...  
 Certificate (if required) ... £ ...  
 (Travelling Expenses, if any, £ ...)  
 Committee's Minute 4th May 1877  
 Character assigned Coups 7A

Surveyor to Lloyd's Register of British and Foreign Shipping.

© 2021 Lloyd's Register Foundation