

# ANNUAL SURVEYS.

36158

No. in Reg. Book. 202 No. 332 Survey held at LONDON Date, first Survey 18 April Last Survey 18 April 1877  
 on the "Cetera" Master Road  
 Tonnage 245 Built at Bideford When built 1874 1 mo.  
 By whom built 289 Cox Owners W & J. Smith  
 Port belonging to LONDON Destined Voyage  
 If Surveyed Afloat or in Dry Dock afloat W. I. Dock

Last Survey, No. 1763 Port of Bideford Classified 13 A1 Years assigned. 1874 Character in Register Book.

Present Condition of the Decks	<u>Good</u>	Treenails	<u>where seen</u>	<u>Good</u>	
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	<u>do</u>	Windlass and Capstan
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	<u>do</u>	Pumps
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>	<u>do</u>	Boats
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>do</u>	<u>do</u>	Masts, Yards, &c.
Planksheers	<u>do</u>	Keelsons	<u>do</u>	<u>do</u>	Condition, how ascertained
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>do</u>	<u>do</u>	Sails
Topsides	<u>do</u>	Ceiling	<u>do</u>	<u>do</u>	Anchors, No. of
Wales	<u>do</u>	Rudder	<u>do</u>	<u>do</u>	Cables
Plank (Bottom) and Counter	<u>where seen</u>	Copper or Y.M.	<u>do</u>	When put on <u>74</u>	Hawsers and Warps
Engine Room Skylights	<u>do</u>	Caulking of Bottom, Deck, & Waterways	<u>do</u>	<u>do</u>	Standing and Running Rigging
Coal Bunker, Openings, Lids, &c.		Scuppers			Hatches

Examined Vessel where practicable and found her in good condition and eligible to remain as classed.  
 Surveyed with part outward cargo on board.

Committee's Minute 8th May 1877 Wm. Congdon  
 Character assigned 13 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. in Reg. Book. 150 No. 591 Survey held at LONDON Date, first Survey 23 April Last Survey 24 April 1877  
 on the "Mercurius" Master Wootton  
 Tonnage 591 Built at Kingardine When built 1867 9 mo.  
 By whom built 552 Wright Owners Grant  
 Port belonging to LONDON Destined Voyage  
 If Surveyed Afloat or in Dry Dock Fletcher's Dock


Last Survey, No. 35226 Port of LONDON Classified 10 A1 Years assigned. 12.75 Character in Register Book.

Present Condition of the Decks	<u>Good</u>	Treenails	<u>where seen</u>	<u>Good</u>	
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	<u>do</u>	Windlass and Capstan
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	<u>do</u>	Pumps
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>	<u>do</u>	Boats
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>do</u>	<u>do</u>	Masts, Yards, &c.
Planksheers	<u>do</u>	Keelsons	<u>do</u>	<u>do</u>	Condition, how ascertained
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>do</u>	<u>do</u>	Sails
Topsides	<u>do</u>	Ceiling	<u>do</u>	<u>do</u>	Anchors, No. of
Wales	<u>do</u>	Rudder	<u>do</u>	<u>do</u>	Cables
Plank (Bottom) and Counter	<u>where seen</u>	Copper or Y.M.	<u>do</u>	When put on <u>75</u>	Hawsers and Warps
Engine Room Skylights	<u>do</u>	Caulking of Bottom, Deck, & Waterways	<u>do</u>	<u>do</u>	Standing and Running Rigging
Coal Bunkers, Openings, Lids, &c.		Scuppers			Hatches

This Vessel appears in good condition and eligible to remain as classed.  
 Surveyed with some kentledge and damaged in hold.  
 It is intended to reclass the ship on her return.

Committee's Minute 8th May 1877 Wm. Congdon  
 Character assigned 10 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

LONG62-0116



*beta*

—

*Inventum*

—



© 2021

Lloyd's Register  
Foundation