

ANNUAL SURVEYS.

36,169

No. in Reg. Book. 722 No. 19 Survey held at London Date, first Survey 20 April Last Survey 20 April 1877
 on the "Emmore" Master Kennedy
 Tonnage 540 Built at 19 Bristol When built 1858
 By whom built Green Owners Scrutton &
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Fletcher's dock

Recd 3. 5. 77.

Last Survey, No. 35292 Port of London

Classed 11 Years assigned. At 2. 76 Character in Register Book. Rest 76-6 yr

Present Condition of the Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors, No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper or Y.M.	Standing and Running Rigging
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	Hatches
General Observations, Opinion as to Class, &c.	Coal Bunker, Openings, Lids, &c.	
	Scuppers	
	Cargo and Main Hatchways	

This Vessel appears in good Condition and eligible to remain as classed.

Committee's Minute 11th May 1877 Thos Congdon
 Character assigned 11A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) DBW Paid _____ 18 _____

No. 531 Survey held at London Date, first Survey 23 April Last Survey 2 May 1877
 on the "Leanne" Master _____
 Tonnage 176 1/2 Built at Sunderland When built 1870 2 mo.
 By whom built Crown Owners 19 minor Pers.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Fletcher's dock

Last Survey, No. 34874 Port of London

Classed 10 Years assigned. At 3. 75 Character in Register Book. H.F. 75

Present Condition of the Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors, No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper or Y.M.	Standing and Running Rigging
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	Hatches
General Observations, Opinion as to Class, &c.	Coal Bunkers, Openings, Lids, &c.	
	Scuppers	
	Cargo and Main Hatchways	


This Vessel appears in good Condition and eligible to remain as classed.
Lower rigging new.

Committee's Minute 11th May 1877 Thos Congdon
 Character assigned 10A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) DBW Paid _____ 18 _____

1210-299001

Emmure

—
Assane
—



© 2021

Lloyd's Register
Foundation