


ANNUAL SURVEYS.

36195
Paid 12.5.77

No. in Reg. Book. 267 No. 1 Survey held at London Date, first Survey 1st May Last Survey 1st May 1877
 on the "Agnes Rose" Master How
 Tonnage 947 Built at Merdeen When built 1867 - 3 mo.
 By whom built Dubie Owners Rose &
 Port belonging to Merdeen Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Carters dry dock



Last Survey, No. 34793 Port of London Classed 11 Years assigned 11 Character in Register Book A16.75
H.T.72

Present Condition of the Decks _____ Waterways _____ Comings _____ Upper Deck Beams & Fastenings _____ Lower Deck Beams & Fastenings _____ Planksheers _____ Sheerstrakes _____ Topsides _____ Wales _____ Plank (Bottom) and Counter _____ Engine Room Skylights _____ General Observations, Opinion as to Class, &c. _____	Treenails <u>where seen</u> <u>Good</u> Breasthooks and Stemson <u>do</u> <u>do</u> Transoms, Pointers, and Crutches <u>do</u> <u>do</u> Timbers of the Frame at the Openings <u>do</u> <u>do</u> Ditto ditto at other places <u>do</u> <u>do</u> Keelsons _____ Clamps and Shelves _____ Ceiling _____ Rudder _____ Copper or Y.M. _____ When put on _____ Caulking of Bottom, Deck, & Waterways _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____	Windlass and Capstan _____ Pumps _____ Boats _____ Masts, Yards, &c. <u>Good</u> Condition, how ascertained _____ Sails _____ Anchors, No. of _____ Cables _____ Hawsters and Warps _____ Standing and Running Rigging <u>complete</u> Hatches _____
--	---	--

This vessel appears, where seen, in good condition and eligible to remain as classed.

Surveyed with part outward Cargo on board, and with damage at both ends.

Committee's Minute 18th May 1877 Thos. Congdon
 Character assigned A16.75 TRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in Reg. Book. on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____ Years assigned _____ Character in Register Book _____

Present Condition of the Decks _____ Waterways _____ Comings _____ Upper Deck Beams & Fastenings _____ Lower Deck Beams & Fastenings _____ Planksheers _____ Sheerstrakes _____ Topsides _____ Wales _____ Plank (Bottom) and Counter _____ Engine Room Skylights _____ General Observations, Opinion as to Class, &c. _____	Treenails _____ Breasthooks and Stemson _____ Transoms, Pointers, and Crutches _____ Timbers of the Frame at the Openings _____ Ditto ditto at other places _____ Keelsons _____ Clamps and Shelves _____ Ceiling _____ Rudder _____ Copper or Y.M. _____ When put on _____ Caulking of Bottom, Deck, & Waterways _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____	Windlass and Capstan _____ Pumps _____ Boats _____ Masts, Yards, &c. _____ Condition, how ascertained _____ Sails _____ Anchors, No. of _____ Cables _____ Hawsters and Warps _____ Standing and Running Rigging _____
--	---	---

Committee's Minute _____ 18 _____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____



5310-299101

Agnes Rose



© 2021

Lloyd's Register
Foundation