

ANNUAL SURVEYS.

26,262

Rec. 6.6.77

No. in Reg. Book. **522** No. **135** Survey held at **London** Date, first Survey **18 May** Last Survey **18 May** 18**77**
 on the **"Roseau"** Master **B. Hunt**
 Tonnage **371** Built at **Jersey** When built **1854**
 By whom built **Scrutton** Owners **Scrutton**
 Port belonging to **London** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Hetchers dry dock**

Last Survey, No. **33594** Port of **London** Classed **12** Years assigned. **12** Character in Register Book. **A1 1.74**
 Present Condition of the Decks **Good** Treenails **where seen** **Good** Breasthooks and Stems **do** **do**
 Waterways **do** Transoms, Pointers, and Crutches **do** **do** Windlass and Capstan
 Comings **do** Timbers of the Frame at the Openings **do** **do** Pumps
 Upper Deck Beams & Fastenings **do** Ditto ditto at other places **do** **do** Boats
 Lower Deck Beams & Fastenings **do** Keelsons **do** **do** Masts, Yards, &c. **Good**
 Planksheers **do** Clamps and Shelves **do** **do** Condition, how ascertained
 Sheerstrakes **do** Ceiling **do** **do** Sails **and**
 Topsides **do** Rudder **do** **do** Anchors, No. of
 Wales **do** Copper Y.M. When put on **74** Cables
 Plank (Bottom) **where seen** **do** Caulking of Bottom, Deck, & Waterways **Good** Hawesers and Warps **Complete**
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Metal patched. This vessel appears in good condition and eligible to remain as classed.
Surveyed with ballast and dunnage in hold.

Committee's Minute **15th June, 1877.** **W. Congdon**
 Character assigned **Cowd S.A.** Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **PAID** 18

No. in Reg. Book. **218** No. **S. 100** Survey held at **London** Date, first Survey **19 May** Last Survey **19 May** 18**77**
 on the **"Glenelough"** Master **Coleman**
 Tonnage **414** Built at **Sunderland** When built **1858**
 By whom built **Scrutton** Owners **Scrutton**
 Port belonging to **London** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Hetchers dry dock**

Last Survey, No. **34637** Port of **London** Classed **12** Years assigned. **12** Character in Register Book. **A1 4.75**
 Present Condition of the Decks **Good** Treenails **where seen** **Good** Breasthooks and Stems **do** **do**
 Waterways **do** Transoms, Pointers, and Crutches **do** **do** Windlass and Capstan
 Comings **do** Timbers of the Frame at the Openings **do** **do** Pumps
 Upper Deck Beams & Fastenings **do** Ditto ditto at other places **do** **do** Boats
 Lower Deck Beams & Fastenings **do** Keelsons **do** **do** Masts, Yards, &c. **Good**
 Planksheers **do** Clamps and Shelves **do** **do** Condition, how ascertained
 Sheerstrakes **do** Ceiling **do** **do** Sails **and**
 Topsides **do** Rudder **do** **do** Anchors, No. of
 Wales **do** Copper Y.M. When put on **75** Cables **Complete**
 Plank (Bottom) **where seen** **do** Caulking of Bottom, Deck, & Waterways **Good** Hawesers and Warps
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Metal patched. This vessel appears in good condition and eligible to remain as classed.
Surveyed with ballast and dunnage in the hold.

Committee's Minute **15th June, 1877.** **W. Congdon**
 Character assigned **Cowd S.A.** Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **PAID** 18

2910-299007

Roseau
Georgetown



© 2021

Lloyd's Register
Foundation