

# ANNUAL SURVEYS.

36.264

Rec. 4.6.77

No. in Reg. Book. **No.** 3416 Survey held at **London** Date, first Survey **18 May** Last Survey **18 May** 18 **77**  
 on the **Fontabelle** Master **Arison**  
 Tonnage **337** Built at **Oristol** When built **1855**  
 By whom built **Hill** Owners **Danson**  
 Port belonging to **London** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **Line Rtn dry dock**

Last Survey, No. **2817** Port of **Plymouth** Classed **13** **12.75**  
 Present Condition of the Decks **Good** Treenails **where seen** **Good**  
 Waterways **de** **de** Breasthooks and Stemson **de** **de**  
 Comings **de** **de** Transoms, Pointers, and Crutches **de** **de**  
 Upper Deck Beams & Fastenings **de** **de** Timbers of the Frame at the Openings **de** **de**  
 Lower Deck Beams & Fastenings **de** **de** Ditto ditto at other places **de** **de**  
 Planksheers **Good** Keelsons **de** **de**  
 Sheerstrakes **de** **de** Clamps and Shelves **de** **de**  
 Topsides **de** **de** Ceiling **de** **de**  
 Wales **de** **de** Rudder **de** **de**  
 Plank (Bottom) and Counter **where seen** Copper or Y.M. When put on  
 Engine Room Skylights **de** Caulking of Bottom, Deck, & Waterways **Good**  
 General Observations, Opinion as to Class, &c. **Coal Bunker, Openings, Lids, &c.** Scuppers Cargo and Main Hatchways Hatches

*This vessel appears in good condition and eligible to remain as classed.*

*Surveyed with ballast and dunnage in the hold*

Committee's Minute **15th June, 1877** **J. B. Congdon**  
 Character assigned **Good** Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **Paid** **18**

No. in Reg. Book. **No.** 302 Survey held at **London** Date, first Survey **24 May** Last Survey **24 May** 18 **77**  
 on the **Island Queen** Master **Adams**  
 Tonnage **149** Built at **Salcombe** When built **1853**  
 By whom built **201** Owners **W. A. Russell & Co**  
 Port belonging to **Dartmouth** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **Afloat W. I. dock**

Last Survey, No. **12906** Port of **Newcastle** Classed **12** **6.75**  
 Present Condition of the Decks **Good** Treenails **where seen** **Good**  
 Waterways **de** **de** Breasthooks and Stemson **de** **de**  
 Comings **de** **de** Transoms, Pointers, and Crutches **de** **de**  
 Upper Deck Beams & Fastenings **de** **de** Timbers of the Frame at the Openings **de** **de**  
 Lower Deck Beams & Fastenings **de** **de** Ditto ditto at other places **de** **de**  
 Planksheers **de** **de** Keelsons **de** **de**  
 Sheerstrakes **de** **de** Clamps and Shelves **de** **de**  
 Topsides **de** **de** Ceiling **de** **de**  
 Wales **de** **de** Rudder **de** **de**  
 Plank (Bottom) and Counter **where seen** Copper or Y.M. When put on  
 Engine Room Skylights **de** Caulking of Bottom, Deck, & Waterways **de**  
 General Observations, Opinion as to Class, &c. **Coal Bunkers, Openings, Lids, &c.** Scuppers Cargo and Main Hatchways Hatches

*This vessel appears eligible to remain as classed. Deck Caulked.*

*Surveyed with part cargo on board.*

Committee's Minute **15th June, 1877** **J. B. Congdon**  
 Character assigned **Good** Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **Paid** **18**

102062-0169

Fontainebleau

Island Queen



© 2021

Lloyd's Register  
Foundation