

ANNUAL SURVEYS.

36.270

Reid 14.6.77.

No. in Reg. Book. on the **No. 1123** Survey held at London Date, first Survey 25 May Last Survey 25 May 1877
 Master Guswell
 Tonnage 304 Built at Plymouth When built 1875
 By whom built Marshall Owners Marshall & Short
 Port belonging to Plymouth Destined Voyage _____
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 2452 Port of Plymouth Classed 12 Years assigned 12 Character in Register Book A1
 2.75

Present Condition of the Decks		Treenails <u>where seen</u>	Good	Years assigned	Character in Register Book
Waterways	<u>de</u>	Breasthooks and Stemson	<u>de</u>	12	A1
Comings	<u>de</u>	Transoms, Pointers, and Crutches	<u>de</u>		
Upper Deck Beams & Fastenings	<u>de</u>	Timbers of the Frame at the Openings	<u>de</u>		
Lower Deck Beams & Fastenings	<u>de</u>	Ditto ditto at other places	<u>de</u>		
Plank sheers	<u>de</u>	Keelsons	<u>de</u>		
Sheerstrakes	<u>de</u>	Clamps and Shelves	<u>de</u>		
Topsides	<u>de</u>	Ceiling	<u>de</u>		
Wales	<u>de</u>	Rudder	<u>de</u>		
Plank (Bottom) and Counter	<u>de</u>	Copper or Y.M.	When put on <u>1875</u>		
Engine Room Skylights	<u>de</u>	Caulking of Bottom, Deck, & Waterways			
Coal Bunker, Openings, Lids, &c.		Scuppers			
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways			
		Hatches			

This vessel appears, where seen, in good condition and eligible to remain as classed.
 Surveyed with dunnage, mats &c in hold.

Committee's Minute 15th June, 1877 J. C. Congdon
 Character assigned 12A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. on the **No. 35** Survey held at London Date, first Survey 13 June Last Survey 13 June 1877
 Master R. Mills
 Tonnage 348 Built at Bristol When built 1853
 By whom built _____ Owners Scrutton & Sons
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock afloat - W. I. Dock

Last Survey, No. 34157 Port of London Classed 13 Years assigned 13 Character in Register Book A1
 11.73

Present Condition of the Decks		Treenails <u>where seen</u>	Good	Years assigned	Character in Register Book
Waterways	<u>de</u>	Breasthooks and Stemson	<u>de</u>	13	A1
Comings	<u>de</u>	Transoms, Pointers, and Crutches	<u>de</u>		
Upper Deck Beams & Fastenings	<u>de</u>	Timbers of the Frame at the Openings	<u>de</u>		
Lower Deck Beams & Fastenings	<u>de</u>	Ditto ditto at other places	<u>de</u>		
Plank sheers	<u>de</u>	Keelsons	<u>de</u>		
Sheerstrakes	<u>de</u>	Clamps and Shelves	<u>de</u>		
Topsides	<u>de</u>	Ceiling	<u>de</u>		
Wales	<u>de</u>	Rudder	<u>de</u>		
Plank (Bottom) and Counter	<u>de</u>	Copper or Y.M.	When put on <u>72</u>		
Engine Room Skylights	<u>de</u>	Caulking of Bottom, Deck, & Waterways			
Coal Bunkers, Openings, Lids, &c.		Scuppers			
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways			
		Hatches			

This vessel appears, where seen, in good condition and eligible to remain as classed.
 Surveyed with ballast and dunnage in hold.

Committee's Minute 15th June, 1877 J. C. Congdon
 Character assigned 12A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

1150-299N07



James Brown

—



© 2021

Lloyd's Register
Foundation