

# ANNUAL SURVEYS.

Recd 3-7-77.

No. in Reg. Book. on the **No. 180** Survey held at **London** Date, first Survey **26 June** Last Survey **26 June 1877**  
 Master **Paul**  
 Tonnage **137** Built at **Maldou** When built **1862** 7 no.  
 By whom built **Humpson** Owners **Lucas**  
 Port belonging to **Maldou** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **Afloat. Fletcher's wharf**

Last Survey, No. **11436** Port of **Tunderland**

Years assigned. **9** Character in Register Book. **A1 6.76**  
**A1. S.S. 76. 4yr**

Present Condition of the Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c. <b>Good</b>
Lower Deck Beams & Fastenings	Ditto ditto at other place	Condition, how ascertained
Planksheers <b>Good</b>	Keelsons	Sails <b>and</b>
Sheerstrakes	Clamps and Shelves <b>Good</b>	Anchors, No. of
Topsides	Ceiling	Cables <b>efficient</b>
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter <b>where seen</b>	Copper or Y.M. When put on	Standing and Running Rigging
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	Cargo and Main Hatchways
Coal Bunker, Openings, Lids, &c.	Scuppers	Hatches

General Observations, Opinion as to Class, &c. **This vessel appears eligible to remain as classed.**

Committee's Minute **10th July 1877**  
 Character assigned **A1**  
 Surveyor **J. Congdon**  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. in Reg. Book. on the **No. 885** Survey held at **London** Date, first Survey **28 June** Last Survey **28 June 1877**  
 Master **Mc Kay**  
 Tonnage **994** Built at **Aberdeen** When built **1868** 7 no.  
 By whom built **885** **Outhie** Owners **Outhie**  
 Port belonging to **Aberdeen** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **Afloat S.W.S. Dock**

Last Survey, No. **33083** Port of **London**


Years assigned. **16** Character in Register Book. **A1 10.75**  
**A.T. 75.**

Present Condition of the Decks	Treenails <b>where seen</b>	Windlass and Capstan
Waterways	Breasthooks and Stenson <b>de de</b>	Pumps
Comings	Transoms, Pointers, and Crutches <b>de de</b>	Boats <b>Good</b>
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings <b>de de</b>	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places <b>de de</b>	Condition, how ascertained
Planksheers	Keelsons <b>de de</b>	Sails <b>and</b>
Sheerstrakes	Clamps and Shelves <b>de de</b>	Anchors, No. of
Topsides	Ceiling <b>de de</b>	Cables
Wales	Rudder <b>de de</b>	Hawsers and Warps <b>efficient</b>
Plank (Bottom) and Counter <b>where seen</b>	Copper or Y.M. When put on <b>75</b>	Standing and Running Rigging
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	Cargo and Main Hatchways
Coal Bunkers, Openings, Lids, &c.	Scuppers	Hatches

General Observations, Opinion as to Class, &c. **This vessel appears in good condition and eligible to remain as classed**

Surveyed with ballast in hold  
 Committee's Minute **10th July 1877**  
 Character assigned **A1**  
 Surveyor **J. Congdon**  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

Maldon



© 2021

Lloyd's Register  
Foundation