

ANNUAL SURVEYS.

No. in Reg. Book. **1253** No. **13** Survey held at **London** Date, first Survey **13 July** Last Survey **13 July** 18 **77**
 on the **"Susan Bayley"** Master **Poberts**
 Tonnage **157** Built at **Spurwich** When built **1853**
 By whom built **Bayley** Owners **Banner Bros.**
 Port belonging to **London** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Fletcher's dock**

Last Survey, No. **33613** Port of **London** Classed **13** Years assigned **3.5.76-4.7.76** Character in Register Book **Red**
 Present Condition of the
 Decks **Good** Treenails **Good** Windlass and Capstan
 Waterways **Good** Breasthooks and Stemson **Good** Pumps
 Comings **Good** Transoms, Pointers, and Crutches **Good** Boats **Good**
 Upper Deck Beams & Fastenings **Good** Timbers of the Frame at the Openings **Good** Masts, Yards, &c. **Good**
 Lower Deck Beams & Fastenings **Good** Ditto ditto at other places **Good** Condition, how ascertained **Good**
 Planksheers **Good** Keelsons **Good** Sails **Complete**
 Sheerstrakes **Good** Clamps and Shelves **Good** Anchors, No. of **Complete**
 Topsides **Good** Ceiling **Good** Cables **Complete**
 Wales **Good** Rudder **Good** Hawfers and Warps **Complete**
 Plank (Bottom) and Counter **Good** Copper or Y.M. When put on **Good** Standing and Running Rigging **Complete**
 Engine Room Skylights **Good** Caulking of Bottom, Deck, & Waterways **Good** Cargo and Main Hatchways **Complete**
 General Observations, Opinion as to Class, &c. **Good** Scuppers **Good** Hatches **Complete**

This vessel appears in good condition and eligible to remain as classed.

Committee's Minute **31st July 1877** Character assigned **Good** Surveyor to Lloyd's Register of British and Foreign Shipping. **Thos. Couzdon**
 Certificate (if required) **PAID** 18

No. in Reg. Book. **220** No. **13** Survey held at **London** Date, first Survey **23 July** Last Survey **23 July** 18 **77**
 on the **"Belle of Southsea"** Master **W. Gay**
 Tonnage **548** Built at **Montrou** When built **1865** 8 no.
 By whom built **Birnie** Owners **J. Guthrie**
 Port belonging to **London** Destined Voyage
 If Surveyed Afloat or in Dry Dock **West. L. Dock afloat**

Last Survey, No. **34743** Port of **London** Classed **10** Years assigned **6.7.75** Character in Register Book **Red**
 Present Condition of the
 Decks **Good** Treenails **where seen Good** Windlass and Capstan
 Waterways **de** Breasthooks and Stemson **de de** Pumps
 Comings **de** Transoms, Pointers, and Crutches **de de** Boats
 Upper Deck Beams & Fastenings **de** Timbers of the Frame at the Openings **de de** Masts, Yards, &c. **Good**
 Lower Deck Beams & Fastenings **de** Ditto ditto at other places **de de** Condition, how ascertained **Good**
 Planksheers **de** Keelsons **de de** Sails **Complete**
 Sheerstrakes **de** Clamps and Shelves **de de** Anchors, No. of **Complete**
 Topsides **de** Ceiling **de de** Cables **Complete**
 Wales **de** Rudder **de de** Hawfers and Warps **Complete**
 Plank (Bottom) and Counter **de** Copper or Y.M. When put on **at Singapore 1877** Standing and Running Rigging **Complete**
 Engine Room Skylights **de** Caulking of Bottom, Deck, & Waterways **at Singapore** Cargo and Main Hatchways **Complete**
 General Observations, Opinion as to Class, &c. **Good** Scuppers **Good** Hatches **Complete**

This vessel appears eligible to remain as classed. Surveyed with ballast and part cargo in hold.

This ship was retalled under damage at Singapore in Feb 1877. Bill for mutally produced.

Committee's Minute **31st July 1877** Character assigned **Good** Surveyor to Lloyd's Register of British and Foreign Shipping. **Thos. Couzdon**
 Certificate (if required) **PAID** 18

LON662-0234