

ANNUAL SURVEYS.

36456

recd 20.8.77

No. in Reg. Book. **No.** 35 on the **Ship "Samascus"** Survey held at **London** Date, first Survey **27 June** Last Survey **30th July** 18**77**
 Tonnage **964** Built at **Aberdeen** When built **1857**
 By whom built **Good** Owners **J. Thompson & Co.**
 Port belonging to **Aberdeen** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Greens Lower by lock.**

Last Survey, No. **34829** Port of **London** Classed **S.S. Lon 75-7 yrs** Years assigned **7-75** Character in Register Book **A.1. Red**
 Present Condition of the Decks **Good** Treenails **Good**
 Waterways **"** Breasthooks and Stemson **"**
 Comings **"** Transoms, Pointers, and Crutches **"**
 Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**
 Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**
 Planksheers **"** Keelsons **"**
 Sheerstrakes **"** Clamps and Shelves **"**
 Topsides **"** Ceiling **Ballast in hold**
 Wales **"** Rudder **"**
 Plank (Bottom) and Counter **"** Copper or Y.M. on Fels When put on **1875**
 Engine Room Skylights **"** Caulking of Bottom, Deck, & Waterways **Good**
 Coal Bunker, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **Bottom sighted, yellow metal patched and Painted, defective foremast removed and renewed of iron. This Vessel is now in good and efficient condition and eligible to remain as classed.**

Committee's Minute **24th August. 1877** Character assigned **A.1. in red** Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) **Paid** 18

No. in Reg. Book. **No.** 451 on the **Ship "Highflyer"** Survey held at **London** Date, first Survey **3rd Aug 1877** Last Survey **3rd Aug 1877**
 Tonnage **1012** Built at **London** When built **1861-10 mo**
 By whom built **Green** Owners **R & H. Green.**
 Port belonging to **London** Destined Voyage
 If Surveyed Afloat or in Dry Dock **Greens by lock.**

Last Survey, No. **35715** Port of **London** Classed **Cent. Lon June 76-9 yrs 9-76** Years assigned **1/4** Character in Register Book **A.1.**
 Present Condition of the Decks **Good** Treenails **Good**
 Waterways **"** Breasthooks and Stemson **"**
 Comings **"** Transoms, Pointers, and Crutches **"**
 Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**
 Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**
 Planksheers **"** Keelsons **"**
 Sheerstrakes **"** Clamps and Shelves **"**
 Topsides **"** Ceiling **Ballast in hold**
 Wales **"** Rudder **"**
 Plank (Bottom) and Counter **"** Copper or Y.M. on Fels When put on **1876**
 Engine Room Skylights **"** Caulking of Bottom, Deck, & Waterways **Good**
 Coal Bunkers, Openings, Lids, &c. **"** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**
 General Observations, Opinion as to Class, &c. **Bottom sighted and the yellow metal patched. This Vessel is now in good and efficient condition and eligible to remain as classed.**

Committee's Minute **24th August. 1877** Character assigned **Coups A.1.** Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) **Paid** 18