

ANNUAL SURVEYS.

36.662

Recd 7.11.77- 1877

No. in Reg. Book. 556 No. 18 Survey held at London Date, first Survey 24/10/77 Last Survey 1 Nov Master Price

Tonnage 175 Built at Swansea When built 1870 2mo
By whom built Brown Owners Banner Bros
Port belonging to London Destined Voyage
If Surveyed Afloat or in Dry Dock Fletcher's Dry Dock

Last Survey, No. 36169 Port of London Classed 10 Years assigned. 10 Character in Register Book. 1

Present Condition of the Decks Good Treenails Good 14.T. Low 75
Waterways do Breasthooks and Stemson Good
Comings do Transoms, Pointers, and Crutches Good
Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings where
Lower Deck Beams & Fastenings do Ditto ditto at other places where
Planksheers do Keelsons Good
Sheerstrakes do Clamps and Shelves Good
Topsides do Ceiling seen
Wales do Rudder Good
Plank (Bottom) and Counter do Copper Y.M. over 7 When put on 75
Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers do Cargo and Main Hatchways Good Hatches do

General Observations, Opinion as to Class, &c.
She is now in a good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 9th November, 1877.

Character assigned 10 Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) — Paid — 18

No. in Reg. Book. 313 No. 52 Survey held at London Date, first Survey 1 Nov 847 Last Survey 1 Nov Master Barnes

Tonnage 275 Built at Garmouth When built 1867 5mo
By whom built Geddie Owners CW & W. Gray
Port belonging to — Destined Voyage
If Surveyed Afloat or in Dry Dock Fletcher's Dry Dock

Last Survey, No. 1667 Port of Southampton Classed 9 Years assigned. 9 Character in Register Book. 1

Present Condition of the Decks Good Treenails Good Cont Low May 76. 74. 11. 75
Waterways do Breasthooks and Stemson Good
Comings do Transoms, Pointers, and Crutches Good
Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings where
Lower Deck Beams & Fastenings do Ditto ditto at other places where
Planksheers do Keelsons Good
Sheerstrakes do Clamps and Shelves Good
Topsides do Ceiling seen
Wales do Rudder Good
Plank (Bottom) and Counter do Copper Y.M. over 7 When put on 75
Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers do Cargo and Main Hatchways Good Hatches do

General Observations, Opinion as to Class, &c.
She is now in a good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 9th November, 1877.

Character assigned Cont 7 Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) — Paid — 18