

# ANNUAL SURVEYS.

36.760

Recd 12.12.77

No. in Reg. Book. **386** No. **1** Survey held at **London** Date, first Survey **Nov 21** Last Survey **Dec 11** 1877  
 on the **S John Allan** Master **J. Home**  
 Tonnage **734** Built at **Sunderland** When built **1864** 411  
 By whom built **Briggs** Owners **J H Allan**  
 Port belonging to **London** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **Dry Dock**

Last Survey, No. **46** Port of **Mauritius** Classed **14A1** 7.77  
 Years assigned. **HT Sm 71** Character in Register Book.  
 Present Condition of the  
 Decks **Good** Treennails **Good**  
 Waterways **"** Breasthooks and Stenson **"**  
 Comings **"** Transoms, Pointers, and Crutches **"**  
 Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**  
 Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**  
 Planksheers **"** Keelsons **"**  
 Sheerstrakes **"** Clamps and Shelves **"**  
 Topsides **"** Ceiling **"**  
 Wales **"** Rudder **"**  
 Plank (Bottom) and Counter **"** Copper or Y.M. **Y Metal** When put on **1876**  
 Engine Room Skylights **"** Caulking of **Patched now**  
 Coal Bunker, Openings, Lids, &c. **"** Bottom, Deck, & Waterways **Good**  
 Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c.

*She is now in good condition and entitled to remain as classed*

*Senhouse Martindale*

Committee's Minute 14th December, 1877.

Character assigned **Gen. Comm. 28th March 1878** Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **5/- Paid 19.12.18**  
 No. **1232** Survey held at **London** Date, first Survey **Dec 1877** Last Survey **Dec 1877**  
 on the **S Mopessilite Composite** Master

Tonnage **1013** Built at **Glasgow** When built **1864** 8M  
 By whom built **Stephen** Owners **J Allan & Sons**  
 Port belonging to **London** Destined Voyage  
 If Surveyed Afloat or in Dry Dock **Dry Dock**

Last Survey, No. **35798** Port of **London** Classed **17A1** 11.76  
 Years assigned. **SS Sm 75** Character in Register Book.  
 Present Condition of the  
 Decks **Good** Treennails **Bolt** **Good**  
 Waterways **"** Breasthooks and Stenson **"**  
 Comings **"** Transoms, Pointers, and Crutches **"**  
 Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**  
 Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**  
 Planksheers **"** Keelsons **"**  
 Sheerstrakes **"** Clamps and Shelves **"**  
 Topsides **"** Ceiling **"**  
 Wales **"** Rudder **"**  
 Plank (Bottom) and Counter **"** Copper or Y.M. **Y Metal** When put on **1876**  
 Engine Room Skylights **"** Caulking of **Patched now**  
 Coal Bunkers, Openings, Lids, &c. **"** Bottom, Deck, & Waterways **Good**  
 Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c.

*She is now in good condition and entitled to remain as classed*

*Senhouse Martindale*

Committee's Minute 14th December, 1877.

Character assigned **17A1** Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **5/- Paid** 18