

# ANNUAL SURVEYS.

36.789

No. 22 Survey held at London Date, first Survey ✓ Last Survey 24 Nov 1877  
 No. in on the BK. "Pactolus" Master Bowser  
 Reg. Book. 22 Tonnage 324, 416, 395 Built at Pallion When built 1864-6 mo  
 By whom built Gill Owners Boddington & Co  
 Port belonging to London Destined Voyage   
 If Surveyed Afloat or in Dry Dock Green's lower dock

Last Survey, No. 34320 Port of London

Present Condition of the

Decks 2  
 Waterways 2  
 Comings 2  
 Upper Deck Beams & Fastenings 2  
 Lower Deck Beams & Fastenings Good  
 Planksheers 2  
 Strakes 2  
 Sides 2  
 Bottom and Counter Good

Treenails not seen  
 Breasthooks and Stemson —  
 Transoms, Pointers, and Crutches Good  
 Timbers of the Frame at the Openings Good  
 Ditto ditto at other places not seen  
 Keelsons Good  
 Clamps and Shelves 3 Good when  
 Ceiling 3 seen  
 Rudder Good  
 Copper or Y.M. Y.M. When put on 74  
 Caulking of Bottom, Deck, & Waterways Good

Classed 11 Years assigned. 11 Character in Register Book. A.1.  
 Cook Lon Jun 74 12.74  
 Windlass and Capstan 2 Good  
 Pumps 2  
 Boats 2  
 Masts, Yards, &c. 2  
 Condition, how ascertained from dk  
 Sails 2  
 Anchors, No. of 3 D-18-2 1/2  
 Cables Port seen Good  
 Hawesers and Warps —  
 Standing and Running Rigging —  
 Cargo and Main Hatchways Good Hatches —

Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers —

General Observations, Opinion as to Class, &c.

Surveyed in ballast - Vessel placed in dry dock  
bottom sighted several bolts in rudder braces renewed.  
Metal patched. This vessel was examined as far as possible  
she appeared to be in good condition and as eligible in  
my opinion to remain classed A.1.

Committee's Minute 24th Dec 1877.

Character assigned Comp 4 A 1  
13W

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No.  Survey held at  Date, first Survey  Last Survey 18  
 No. in on the  Master   
 Reg. Book.  Tonnage  Built at  When built   
 By whom built  Owners   
 Port belonging to  Destined Voyage   
 If Surveyed Afloat or in Dry Dock

Last Survey, No.  Port of

Present Condition of the

Decks   
 Waterways   
 Comings   
 Upper Deck Beams & Fastenings   
 Lower Deck Beams & Fastenings   
 Planksheers   
 Sheerstrakes   
 Topsides   
 Wales   
 Plank (Bottom) and Counter

Treenails   
 Breasthooks and Stemson   
 Transoms, Pointers, and Crutches   
 Timbers of the Frame at the Openings   
 Ditto ditto at other places   
 Keelsons   
 Clamps and Shelves   
 Ceiling   
 Rudder   
 Copper or Y.M.  When put on   
 Caulking of Bottom, Deck, & Waterways

Classed  Years assigned.  Character in Register Book.   
 Windlass and Capstan   
 Pumps   
 Boats   
 Masts, Yards, &c.   
 Condition, how ascertained   
 Sails   
 Anchors, No. of   
 Cables   
 Hawesers and Warps   
 Standing and Running Rigging

Engine Room Skylights  Coal Bunkers, Openings, Lids, &c.  Scuppers  Cargo and Main Hatchways  Hatches

General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18