

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** *36* on the *BK Naparima Naparima* Master *R Mills* Survey held at *London* Date, first Survey *Dec 21* Last Survey *Dec 27* 18*77*

Official Number
TONNAGE under Tonnage Deck
Ditto of Spar Deck, or Avning Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage
Crew Space, as per Rule
Register Tonnage, cut on Bedm
Engine Room
Reg. Tons as St'mer, cut on Bm.

Built at *Bristol* When built *1855*
Owners *Scrutton Sons & Co* Port belonging to *London*
Residence
By whom built
Destined Voyage
If Surveyed Afloat or in Dry Dock *Dry at Ballast & Lumber in*

Length of Poop *ft.* Ditto, Forecastle *ft.* Ditto, Raised Quarter Deck *ft.* Years assigned. *13 A 6.77* Character in Register Book.

Last Survey, No. *36270* Port *London* *Classed* *13 A 6.77* *Expire* *68.9.78* *ET Lon. 73*

REPAIRS, OR EXAMINATION AS PER RULE

*At the present time placed in Dry Dock
The yellow metal stripped off and then bright
from the light mark to top of yellow metal and
treennails driven out in alternate frames where dubber
bright and examined.*

Caulked from keel to metal line.

Re yellow metalled on felt to near load line

Renewed one short plank in Starboard buttock barkie and

*The owners was were informed that her class would
expire at the end of this month. The owner left order with
the foreman that I was only to survey her under the yellow
metal. The decks were much lumbered up and where seen
were much worn.*

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

*Owing to what is stated above in my
opinion she ought to have Expired placed
against her name in the Register Book*

Senhouse Martindale

The Amount of Entry Fee ... £ ... received by me, *JH*

Dec 1. 78 Special ... £ ... *5 Jan 1878*

Certificate (if required) ... £ ...

(Travelling Expenses, if any, £ ...)

Committee's Minute

11th January, 1878.

Character assigned

*Comp 68-9-12.77
Mw 77
DBW*

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register
Foundation

LON662-0422