

REPORT of SURVEY for REPAIRS, &c.

Recd 3.8.76
36.9.43

No. in Reg. Book. **No.** Survey held at London Date, first Survey July 3 Last Survey Aug 22 1876

on the BK Fitzroy Master Bush

TONNAGE under Tonnage Deck 510.63 Built at Sunderland When built 1863 YEAR. MONTH.

Ditto of Spar Deck, or Awning Deck 62.46 Owners J Wilson Port belonging to London

Ditto of Poop 573.09 Residence Reverell

Ditto of Raised Or. Dk. 573.09 By whom built Reverell Destined Voyage

Ditto of Houses on Deck If Surveyed Afloat or in Dry Dock Dry Dock

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St' mer, cut on Bm.

Length of Poop 45.6 ft. Ditto, Forecastle Monkey ft. Ditto, Raised Quarter Deck ft.

Last Survey, No. 33989 Port London Classed 15A 5.76
88 Jan 14 1874

REPAIRS, OR EXAMINATION AS PER RULE

At present the Yellow Metal stripped
caulked from keel to top of Wales and
Re Yellow Metal on felt to load line

Cause of Repairs to be clearly stated.

Present Condition of the		Treenails		Windlass and Capstan	
Decks	<u>Good</u>	Bolts	<u>Good</u>		
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Pumps	
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Boats	
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the openings	<u>"</u>	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto Ditto at other places	<u>"</u>	Condition, how ascertained	<u>Sufficient</u>
Planksheers	<u>"</u>	Keelsons	<u>"</u>	Sails	<u>where</u>
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>	Anchors No. of <u>10</u>	<u>they</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>	Cables	<u>could</u>
Wales	<u>"</u>	Rudder	<u>"</u>	Hawsers and Warps	<u>be seen</u>
Plank (Bottom) and Counter	<u>"</u>	Copper <u>Y.M. on felt</u> When put on <u>Now</u>		Standing & Running Rigging	
Engine Room Skylights	<u>"</u>	Caulking of <u>Bottom, Deck, & Waterways</u>	<u>Good</u>		
Coal Bunker, Openings, Lids, &c.	<u>"</u>	Scuppers	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
General Observations, Opinion as to Class, &c.					

She is now in an efficient state
and entitled to remain as classed

Senhouse Martindale

The Amount of Entry Fee ... £ ... received by me, }
4/8/76 Special ... £ 1 : 1 : }
Certificate (if required) ... £ ... }
(Travelling Expenses, if any, £ ...)

Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute 8th February 1876

Character assigned 15A
BW Y.M. on felt



© 2021

Lloyd's Register Foundation

LON 662-0456