

REPORT of SURVEY for REPAIRS, &c.

No.

No. in
Reg. Book.

Survey held at

London

Date, first Survey

21st Mar

Last Survey

21st Mar. 1878

5 on the

Bn. "G. B. Gradwell"

Master

W. G. Tasker

TONNAGE under Tonnage Deck

15.6

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

15.6

Crew Space, as per Rule

Register Tonnage, cut on Beam

14.6

Engine Room

Reg. Tons as St^rmer, cut on Bm.

Built at

Appldr

When built

1873

Owners

Burnitt & Co

Port belonging to

London

Residence

By whom built

Book

Destined Voyage

Newfoundland

If Surveyed Afloat or in Dry Dock

Afloat

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

36466

Port

London

Classed

11 A.1.

REPAIRS, OR EXAMINATION AS PER RULE

To examine new Chain Cables.

Now supplied 172 fathoms of 1 inch stud link Chain Cable, which has been tested at Lloyd's Proving House at Tipton, Breaking strain 27 tons and Tensile strain 18 tons, the Certificates are signed by W. L. R. Ditt and are dated 28th February 1878.

The Rule requires this vessel to be supplied with 165 fathoms of 1 5/16 Chain Cable, which was the size originally supplied to the ship, but the Owners have now changed these for those mentioned above to meet the Club requirements.

Present Condition of the

Decks

good

Waterways

do

Comings

do

Upper Deck Beams & Fastenings

do

Lower Deck Beams & Fastenings

none

Planksheers

good

Sheerstrakes

do

Topsides

do

Wales

do

Plank (Bottom) and Counter

do

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

good

Cargo and Main Hatchways

good

Hatches good

General Observations, Opinion as to Class, &c.

Treenails

where seen good

Breasthooks and Stemson

do

Transoms, Pointers, and Crutches

do

Timbers of the Frame at the openings

do

Ditto Ditto

at other places not seen

Keelsons

good

Clamps and Shelves

do

Ceiling

do where seen

Rudder

good

Copper

When put on

Caulking of

Bottom, Deck, & Waterways

good

Windlass and Capstan

good

Pumps

Two

do

Boats

do

Masts, Yards, &c.

do

Condition, how ascertained

From Deck

Sails

Complete

Anchors

No. of

2 B, 1 H, 1 K

Cables

172 fathoms of 1"

Hawsers and Warps

good & sufft

Standing & Running Rigging

do

The Amount of Entry Fee£

22/3/78 Special

... ..£

Certificate (if required)

... ..£

(Travelling Expenses, if any, £)

Committee's Minute

23rd March.

1878.

Character assigned

11A

DRW

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation

LON662-0509