

REPORT of ^{Survey of owner} SURVEY for REPAIRS, &c.

No. 135 on the By Adela Survey held at London Date, first Survey Dec 4/77 Last Survey April 15 1878
No. in Reg. Book. 135 Master Adela YEAR. 1865 MONTH. 8
TONNAGE under Tonnage Deck 215 Built at Lyons When built 1865
Ditto of Spar Deck, or Awning Deck 215 Owners Adela Port belonging to Adela
Ditto of Poop 215 Residence Adela
Ditto of Raised Qr. Dk. 215 By whom built Adams Destined Voyage Adams
Ditto of Houses on Deck 215 If Surveyed Afloat or in Dry Dock Ballast & Cargo
Official Number 227 Gross Tonnage 227 Register Tonnage, out on Beam 227
Engine Room 227 Reg. Tons as St' mer, out on Bm. 227
Length of Poop 227 ft. Ditto, Forecastle 227 ft. Ditto, Raised Quarter Deck 227
Last Survey, No. 227 Port Falmouth Classed 1865 9.76
General Survey May 75-8-78

REPAIRS, OR EXAMINATION AS PER RULE

In December last I accidentally saw this vessel on the beach. I examined her as far as practicable and could not find any thing wrong, although it was stated she had been on the ground during her late voyage. There was no ladder to get in the hold and she was taken to the buoy in the West India dock and laid up in sale, the late owner promising to inform me when a ladder was supplied but never did. I found her again lately in St Katherine's dock with her cargo in and a French crew on board (but no captain) and they could not speak English nor give me any information respecting her.

Present Condition of the	Good	Treenails	When seen in	Windlass and Capstan	
Decks	Good	Breasthooks and Stemson	"	Pumps	
Waterways	"	Transoms, Pointers, and Crutches	Not seen	Boats	
Comings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	Good & sufficient
Upper Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	When seen
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails	When seen
Planksheers	"	Clamps and Shelves	"	Anchors No. of 3 lbs 12 & 16 lbs	They are
Sheerstrakes	"	Ceiling	Good	Cables	When seen
Topsides	"	Rudder	Good	Hawsers and Warps	When seen
Wales	"	Copper <u>yellow</u> When put on	76	Standing & Running Rigging	When seen
Plank (Bottom) and Counter	"	Caulking of	Good	Cargo and Main Hatchways	Good
Engine Room Skylights	"	Bottom, Deck, & Waterways	Good	Hatches	Good
Coal Bunker, Openings, Lids, &c.	"	Scuppers	Good		
General Observations, Opinion as to Class, &c.					

She is now in good condition where she could be seen and in my opinion entitled to remain as classed

Seahouse Martindale

The Amount of Entry Fee ... £ : : received by me, }
Special ... £ : : 187
Certificate (if required) ... £ : :
(Travelling Expenses, if any, £)
Committee's Minute
Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

26th April, 1878.

Seahouse Martindale
Classed as classed
1878