

ANNUAL SURVEYS.

No. in Reg. Book. **No.** 68 Survey held at London Date, first Survey Dec 29. 1877 Last Survey Dec 24 1877
 on the BK Zayda Master S Griffiths
 Tonnage 210 Built at Bideford When built 1869-11/11
 By whom built Johnson Owners W Gold
 Port belonging to Bideford Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Gridiron, Sundry & Lumber in

Last Survey, No. 25301 Port of (~~Liverpool~~) Classed 14A 11.76
 Present Condition of the Decks Good Treenails Good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Sides " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Y Metal When put on 76
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. She is now in good condition and entitled to remain as classed.

Committee's Minute 1st January, 1878. Character assigned 14A 11.76 Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) Paid 18

No. in Reg. Book. **No.** 463 Survey held at London Date, first Survey Dec 18 1877
 on the BK Plover (Ship in Port) Master W Bay
 Tonnage 414 Built at Sunderland When built 1858
 By whom built _____ Owners Scrutton Sons & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Afloat & most of her cargo in

Last Survey, No. 35753 Port of London Classed 18A 10.76
 Present Condition of the More seen Good Treenails Where seen Good
 Breasthooks and Stenson "
 Transoms, Pointers, and Crutches "
 Timbers of the Frame at the Openings "
 Ditto ditto at other places "
 Keelsons "
 Clamps and Shelves "
 Ceiling "
 Rudder "
 Copper or Y.M. Y Metal When put on 76
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. She is now in good condition and entitled to remain as classed.

Committee's Minute 1st January, 1878. Character assigned 18A 10.76 Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) Paid 18