

Alteration of Rig  
37.250  
REPORT of SURVEY for REPAIRS, &c.

No. \_\_\_\_\_  
No. in Reg. Book. \_\_\_\_\_ Survey held at London Date, first Survey May 4<sup>th</sup> Last Survey May 31<sup>st</sup> 1878  
357 on the BK Troops Master M. Bury  
TONNAGE under Tonnage Deck 327 Built at Littlehampton When built 1876 - 7  
Ditto of Spar Deck, or Awning Deck \_\_\_\_\_ Owners A. A. W. Lister Port belonging to London  
Ditto of Poop \_\_\_\_\_  
Ditto of Raised Qr. Dk. \_\_\_\_\_  
Ditto of Houses on Deck \_\_\_\_\_  
Ditto of Forecastle \_\_\_\_\_  
Gross Tonnage 377 Residence \_\_\_\_\_  
Crew Space, as per Rule \_\_\_\_\_ By whom built Harvey Destined Voyage \_\_\_\_\_  
Register Tonnage, cut on Beam 368 If Surveyed Afloat or in Dry Dock By HK  
Engine Room \_\_\_\_\_  
Reg. Tons as St<sup>r</sup>mer, cut on Bm. \_\_\_\_\_

Length of Poop 1 ft. Ditto, Forecastle 1 ft. Ditto, Raised Quarter Deck 10 1/2 ft. Years assigned. 12 A 1 Character in Register Book. 9.76  
Last Survey, No. 356 81 Port London Classed 12 A 1

REPAIRS, OR EXAMINATION AS PER RULE

at present alteration of Rig into a Barque.  
New Main Mast. Main Mast & Topgallant Mast  
Main Yard 2 Sprail Yards. Topgallant Mast  
Mizen Mast Empenned at lower end. New Mizen Mast  
Yellow Metal Patched.

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson	"	Pumps	
Comings	"	Transoms, Pointers, and Crutches	"	Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	<u>Good &amp; sufficient</u>
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	<u>where they could be seen</u>
Planksheers	"	Keelsons	"	Sails	
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of <u>12</u>	
Topsides	"	Ceiling	"	Cables	
Wales	"	Rudder	"	Hawsers and Warps	
Plank (Bottom) and Counter	"	Copper <u>7 Metal</u> When put on <u>1876</u>		Standing & Running Rigging	
		Caulking of <u>Patched now</u>			
Engine Room Skylights	<u>Good</u>	Bottom, Deck, & Waterways	<u>Good</u>		
Coal Bunker, Openings, Lids, &c.	<u>Good</u>			Cargo and Main Hatchways	<u>Good</u>
Scuppers	<u>Good</u>			Hatches	<u>Good</u>

General Observations, Opinion as to Class, &c.

She is now in good condition  
and entitled to remain as Classed

Leithhouse Martindale

The Amount of Entry Fee ... £ : : received by me, }  
3/6/48 Special ... £ / : / 23 July 1878 }  
Certificate (if required) ... £ : :  
(Travelling Expenses, if any, £ )

Committee's Minute 1<sup>st</sup> June 1878

Character assigned 12 A 1

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation

LON 663-0041