

REPORT of SURVEY for REPAIRS, &c.

37.285

Recd 17.6.78

No. 32 on the BR Ethel (Company) Master A Rob
 No. in Reg. Book. 411 Survey held at London Date, first Survey April 1878 Last Survey June 11 1878
 Tonnage under Tonnage Deck 496 Built at Sunderland When built 1866 3
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 556 Owners Jennick & Co Port belonging to London
 Crew Space, as per Rule
 Register Tonnage, cut on Beam 556 Residence
 Engine Room By whom built Pile Destined Voyage
 Reg. Tons as St' mer, cut on Bm. If Surveyed Afloat or in Dry Dock afloat

Length of Poop 44 ft. Ditto, Forecastle 1 ft. Ditto, Raised Quarter Deck 1 ft. Years assigned. 14A 5.77
 Last Survey, No. 36226 Port London Character in Register Book.
 HT Lm 70, SS Lm 77

REPAIRS, OR EXAMINATION AS PER RULE

at present owing to Damage
 Renewed Starboard side 12 Roughstee Stanchions
 East India Leak. Main Rail of Oak

Port side 11 Roughstee Stanchions East India Leak.
 Main Rail oak.
 New Bronz Spuit

Cham Cable or Lark & examine 240 patterns made

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Belts</u>	<u>Good</u>	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson	"	"	Pumps	
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	<u>Good & sufficient</u>
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	<u>where</u>
Planksheers	"	Keelsons	"	"	Sails	<u>They could be seen</u>
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors No. of <u>3</u> <u>1/2</u> <u>1/2</u>	
Topsides	"	Ceiling	"	"	Cables	
Wales	"	Rudder	"	"	Hawsers and Warps	
Plank (Bottom) and Counter	"	Copper of Metal When put on <u>77</u>	"	"	Standing & Running Rigging	
Engine Room Skylights	"	Caulking of	"	"	Cargo and Main Hatchways	<u>Good</u>
Coal Bunker, Openings, Lids, &c.	"	Bottom, Deck, & Waterways	"	"	Hatches	<u>Good</u>
Scuppers	"		"	"		

General Observations, Opinion as to Class, &c.

She is now in good condition
 and entitled to remain as Classed

Senhouse Martindale

The Amount of Entry Fee ... £ 2 : 2 : received by me, 23 July 1878
 Special ... £ 2 : 2 :
 Certificate (if required) ... £ : :
 (Travelling Expenses, if any, £)

Committee's Minute

21st June, 1878

Character assigned

14A

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation

LON663-0052