

# ANNUAL SURVEYS.

37.4 55

Dec 22. 8. 78

No. 217 Survey held at London Date, first Survey 24<sup>th</sup> July Last Survey 17<sup>th</sup> August 18 78  
 No. in on the Ship "Renown" Master R. Hildash  
 Reg. Book. 217 Tonnage 1293 Built at London When built 1860 5<sup>th</sup> mo.  
 By whom built Green Owners R. & H. Green  
 Port belonging to London Destined Voyage  
 If Surveyed Afloat or in Dry Dock East India Dock

Last Survey, No. 36560 Port of London

Classed 14 Years assigned 14 Character in Register Book. A1  
 9.77

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good where seen</u>	
Waterways		Breasthooks and Stemson	<u>do</u>	Windlass and Capstan <u>Good</u>
Comings		Transoms, Pointers, and Crutches	<u>do</u>	Pumps
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	<u>do</u>	Boats <u>5 in number</u>
Lower Deck Beams & Fastenings		Ditto ditto at other places	<u>do</u>	Masts, Yards, &c.
Planksheers		Keelsons	<u>do</u>	Condition, how ascertained <u>from dk &amp; enquiry</u>
Sheerstrakes		Clamps and Shelves	<u>do</u>	Sails <u>well found</u>
Topsides		Ceiling	<u>do</u>	Anchors, No. of <u>3 Bow</u> 1 <u>stern</u> of <u>10 cwt</u> & 1 <u>hedge</u>
Wales		Rudder	<u>do</u>	Cables <u>complete</u>
Plank (Bottom) and Counter <u>where seen</u>		Copper or Y.M. <u>yellow metal</u> When put on <u>77</u>		Hawsers and Warps <u>sufficient</u>
Engine Room Skylights		Caulking of		Standing and Running Riggings
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways <u>good where seen</u>		
General Observations, Opinion as to Class, &c.	<u>Surveyed with ballast &amp; cargo in hold.</u>			

We have acquainted the owner in due time that for completion of the equipment an additional Stream Anchor of 13 cwt should be supplied, but on visiting the vessel when on the point of sailing this anchor was not on board & she has now sailed without it. The owner has however expressed his willingness to supply this deficiency on the return of the vessel from her present voyage. With this exception she is now in good, efficient condition & eligible in our opinion to remain as classed, if the committee be pleased to grant the figure 1. H. Paulsen

Committee's Minute 27<sup>th</sup> August, 1878.

Character assigned Classed 9 A1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. 669 Survey held at London Date, first Survey 15<sup>th</sup> August Last Survey 15<sup>th</sup> August 18 78

No. in on the Barque "Griffin" Master J. Loughton  
 Reg. Book. 669 Tonnage 369 Built at Sunderland When built 1857  
 By whom built G. Robertson Owners G. Robertson  
 Port belonging to N. Shlds Destined Voyage  
 If Surveyed Afloat or in Dry Dock West Ind. Dry Dock

Last Survey, No. 4593 Port of Glasgow

Classed 9 Years assigned 9 Character in Register Book. A1  
 2.78

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good where seen</u>	
Waterways		Breasthooks and Stemson	<u>do</u>	Windlass and Capstan <u>Good</u>
Comings		Transoms, Pointers, and Crutches	<u>do</u>	Pumps
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	<u>do</u>	Boats
Lower Deck Beams & Fastenings		Ditto ditto at other places	<u>do</u>	Masts, Yards, &c.
Planksheers		Keelsons	<u>do</u>	Condition, how ascertained <u>from dk &amp; enquiry</u>
Sheerstrakes		Clamps and Shelves	<u>do</u>	Sails <u>well found</u>
Topsides		Ceiling	<u>do</u>	Anchors, No. of <u>3 Bow</u> 1 <u>stern</u> 2 <u>hedges</u>
Wales		Rudder <u>good</u>		Cables <u>complete</u>
Plank (Bottom) and Counter		Copper or Y.M. <u>do</u> When put on <u>1878</u>		Hawsers and Warps <u>suffic</u>
Engine Room Skylights		Caulking of		Standing and Running Riggings
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways <u>good</u>		
General Observations, Opinion as to Class, &c.	<u>Bottom sighted &amp; y.m. sheathing examined &amp; repaired.</u>			

This vessel is now in good & efficient condition, eligible in

my opinion to remain as classed.

The owners have been acquainted that Half Time survey is nearly due & have decided to have this survey held on a future occasion.

Committee's Minute 27<sup>th</sup> August, 1878.

Character assigned Classed 9 A1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18