

No. Survey held at London Date, first Survey Aug 15 Last Survey Aug 19th 1878
 in Book. on the SS Tanefan Master Geary 37456
 Tonnage 876 Built at Newcastle When built 1872-2M
 By whom built Palmer Owners J Pennick & Son
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Porton

Last Survey, No. 28137 Port of London Classed 100A 8.77
 Years assigned. SS Off 101-76 Character in Register Book.

Present Condition of the	<u>good</u>	Treenails <u>Rivets</u>	<u>good</u>	Windlass and Capstan	<u> </u>
Decks	<u> </u>	Breasthooks and Stemson	<u> </u>	Pumps	<u> </u>
Waterways	<u> </u>	Transoms, Pointers, and Crutches	<u> </u>	Boats	<u> </u>
Openings	<u> </u>	Timbers of the Frame at the Openings	<u> </u>	Masts, Yards, &c.	<u>good & sufficient</u>
Upper Deck Beams & Fastenings	<u> </u>	Ditto ditto at other places	<u> </u>	Condition, how ascertained	<u> </u>
Lower Deck Beams & Fastenings	<u> </u>	Keelsons	<u> </u>	Sails	<u> </u>
Planksheers	<u> </u>	Clamps and Shelves	<u> </u>	Anchors, No. of <u>3 No. 8 & 12 lbs</u>	<u> </u>
Sheerstrakes	<u> </u>	Ceiling	<u> </u>	Cables	<u> </u>
Topsides	<u> </u>	Rudder	<u> </u>	Hawsers and Warps	<u> </u>
Wales	<u> </u>	Copper or Y.M. <u>Copper</u> When put on <u>new</u>	<u> </u>	Standing and Running Rigging	<u> </u>
Plank (Bottom) and Counter	<u> </u>	Caulking of Bottom, Deck, & Waterways	<u>good</u>	Engine Room Skylights <u>good</u>	<u> </u>
Coal Bunkers, Openings, Lids, &c.	<u>good</u>	Scuppers	<u>good</u>	Cargo and Main Hatchways <u>good</u>	<u> </u>
Hatches	<u>good</u>	General Observations, Opinion as to Class, &c.	<u>Bottom Scraped & braked</u>		

She is now in good condition and entitled to remain as classed

Committee's Minute 27th August 1878.
 Character assigned 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping. Senhaver Martindale
 Certificate (if required) Paid 18