

REPORT of SURVEY for REPAIRS, &c.

37.550

No. 1325 on the 184 Mountain Ash Master W. Pinciman
 No. in Reg. Book. 1325 Survey held at London Date, first Survey 1 Oct 1878 Last Survey 1 October 1878

Tonnage under Tonnage Deck <u>406</u> Ditto of Spar Deck, or Awning Deck Ditto of Poop Ditto of Raised Qr. Dk. Ditto of Houses on Deck Ditto of Forecastle Gross Tonnage <u>450</u> Crew Space, as per Rule Register Tonnage, cut on Beam <u>428</u> Engine Room Reg. Tons as St' mer, cut on Bm.	Built at <u>Trom</u> Owners <u>J. Jacobs</u> Residence <u>150 & 157 Leechurch St</u> By whom built <u>Wm. S. Co</u> If Surveyed Afloat or in Dry Dock <u>Bull Head Dry Dock</u>	When built <u>1862</u> <u>9</u> Port belonging to <u>London</u> Destined Voyage If Surveyed Afloat or in Dry Dock <u>Bull Head Dry Dock</u>
---	---	--

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned 11 Character in Register Book L
 Last Survey, No. 357404 Port London Classed 11 1
London Oct June 14 4 76

REPAIRS, OR EXAMINATION AS PER RULE on Annual Survey
Change of Owners.
Vessel placed in dry dock and bottom sighted.
She is due for half time survey - but upon application by the present
owner - she has been allowed to proceed upon her intended voyage
without undergoing that survey - (Copy of letter sent to owner
attached hereto)

Present Condition of the			
Decks	<u>Good</u>	Treenails	<u>Good</u>
Waterways	<u>D</u>	Breasthooks and Stemson	
Comings	<u>D</u>	Transoms, Pointers, and Crutches	
Upper Deck Beams & Fastenings	<u>D</u>	Timbers of the Frame at the openings	
Lower Deck Beams & Fastenings	<u>D</u>	Ditto Ditto at other places	<u>where</u>
Plank sheers	<u>D</u>	Keelsons	
Steerstrakes	<u>D</u>	Clamps and Shelves	
Copsides	<u>D</u>	Ceiling	<u>been</u>
Wales	<u>D</u>	Rudder	<u>Good</u>
Plank (Bottom) and Counter <u>where seen</u>	<u>D</u>	Copper <u>1 1/2</u> When put on <u>1876</u>	
Engine Room Skylights	<u>Coal Bunker, Openings, Lids, &c.</u>	Caulking of	
		Bottom, Deck, & Waterways	<u>Good</u>
		Scuppers	<u>D</u>
		Cargo and Main Hatchways	<u>D</u>
		Hatches	<u>D</u>

General Observations, Opinion as to Class, &c.
She is now in a good and efficient condition and is eligible
in my opinion to remain as classed.

The Amount of Entry Fee £ 1 : - : - received by me, [Signature]
9/10/78 Special £ : : : - 22nd 1878
 Certificate (if required) £ : : : -
 (Travelling Expenses, if any, £)

Committee's Minute 11th October, 1878.
 Character assigned Good
[Signature]



The Surveyors are requested not to write on or below the space for Committee's Minute.