

ANNUAL SURVEYS.

No. 233 Survey held at London Date, first Survey 13 Jan^r 1879 Last Survey 17 January 1879
 No. in on the S. Orient Master James
 Reg. Book. 233 Tonnage 1033 Built at London When built 1853 12 ms
 By whom built Pilke Owners Anderson Anderson & Co
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Nelson Dry Dock

Last Survey, No. 36335 Port of London Classed 10 Years assigned. 10 Character in Register Book. A 1

Present Condition of the Decks Worn but - Good Treenails Good Rest London 72. Signs
 Waterways Good Breasthooks and Stemson Good HT. Lon. 76. 6.76
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places where
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter where seen Copper or Y.M. Good When put on 76
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c. Wood placed in dry dock, hung in shores and keel beam caulked - Yellow metal sheathing patched. 3 ceiling planks renewed and several others pieced. She now appears to be in a good and efficient condition and is eligible in my opinion to remain as classed.

Committee's Minute 24th January, 1879.

Character assigned Rest & 1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 57 Paid 8 Sept 1879 C. H. H.

No. 148 Survey held at London Date, first Survey 14 Jan^r 1879 Last Survey 15 Jan^r 1879
 No. in on the Bⁿ Edina Master Myatt
 Reg. Book. 148 Tonnage 249 Built at P. & S. Island When built 1874 4 ms
 By whom built Peake Owners Mersey Shipwrecking Co^{rs}
 Port belonging to P. & S. Island Destined Voyage
 If Surveyed Afloat or in Dry Dock On gun dock ways at nearly low water

Last Survey, No. 25438 Port of Liverpool Classed 7 Years assigned. 7 Character in Register Book. A 1

Present Condition of the Decks Good Treenails Good 9.77
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places where
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. mer 7 When put on 77
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c. She is now in a good and efficient condition and is eligible in my opinion to remain as classed.

Committee's Minute 24th January, 1879.

Character assigned 7 1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 57 Paid 18