

37.918
REPORT of SURVEY for REPAIRS, &c.

No. _____
No. in Reg. Book. _____ Survey held at London Date, first Survey 2nd Feb Last Survey 5th March 1879
36 on the Ship "Sunphale Castle" Master A. Hilder
TONNAGE under Tonnage Deck 8644 YEAR. MONTH.
Ditto of Spar Deck, or Awning Deck _____
Ditto of Poop _____
Ditto of Raised Qr. Dk. _____
Ditto of Houses on Deck _____
Ditto of Forecastle _____
Gross Tonnage 720
Crew Space, as per Rule _____
Register Tonnage, cut on Beam 720
Engine Room _____
Reg. Tons as St'mer, cut on Bm. _____
Built at Sunderland When built 1861 9
Owners J. H. Allan Port belonging to London
Residence _____
By whom built Laing Destined Voyage _____
If Surveyed Afloat or in Dry Dock Union by lock & afloat
Length of Poop _____ ft. Ditto, Forecastle _____ ft. Ditto, Raised Quarter Deck _____ ft. Years assigned. Character in Register Book.
Last Survey, No. 35915 Port London Classed 14 A.1.
REPAIRS, OR EXAMINATION AS PER RULE Repairs &c. Cong. Lon. June 76-9 12-76

Bottom examined yellow metal sheathing removed, Rudder unhung and the main piece renewed with English Oak, Vessel recaulked from keel to gunwale, and the bottom sheathed with yellow metal over felt.

Present Condition of the
Decks Good
Waterways —
Comings —
Upper Deck Beams & Fastenings —
Lower Deck Beams & Fastenings —
Plank sheers —
Sheerstrakes —
Topsides —
Wales —
Plank (Bottom) and Counter —
Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. This Vessel is now in good and efficient condition and in my opinion eligible to remain as Classed.
Treenails Good
Breasthooks and Stemson —
Transoms, Pointers, and Crutches —
Timbers of the Frame at the openings —
Ditto Ditto at other places —
Keelsons —
Clamps and Shelves —
Ceiling —
Rudder —
Gopper Y. Ab. 7 When put on now
Caulking of —
Bottom, Deck, & Waterways Good
Windlass and Capstan Good
Pumps —
Boats —
Masts, Yards, &c. —
Condition, how ascertained From Deck
Sails Good
Anchors No. of 3 B. 10 1/2 LK.
Cables Good
Hawsers and Warps Good
Standing & Running Rigging Good

The Amount of Entry Fee ... £ " : " : received by me, }
4/3/79 Special ... £ 2 : 2 : 1879 }
Certificate (if required) ... £ : 5 :
(Travelling Expenses, if any, £)
Committee's Minute 11th March, 1879.
Character assigned

Thos Wm Blayell.
Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation

LON663-0300