

REPORT of SURVEY for REPAIRS, &c.

34949

(Regd 19 3 79)

Survey held at London Date, first Survey 20 Feb^{ry} 1879 Last Survey 18th March 1879
 on the B^x Ocean Rover. (Composite) Master Milkinson
 Tonnage under Tonnage Deck 577 Built at Sunderland When built 1867
 Ditto of Spar Deck, or Arming Deck Owners Glover Bros Port belonging to London
 Ditto of Poop Residence
 Ditto of Raised Qr. Dk. By whom built Hompson Destined Voyage N. Indies
 Ditto of Houses on Deck If Surveyed Afloat or in Dry Dock Afloat in the London Docks
 Ditto of Forecastle Gross Tonnage 548
 Crew Space, as per Rule Register Tonnage, cut on Beam 548
 Engine Room Reg. Tons as St^rmer, cut on Bm.

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.
 Last Survey, No. 56 Port Marseilles Classed 16 A 1
 HT. Msl. 77 SS. Msl. 77

REPAIRS, OR EXAMINATION AS PER RULE in Annual Survey.

Vessel surveyed afloat with ballast in hold.
 Spars examined from aloft - slight defects removed from behind starboard
 cheeks of fore and main masts; pieces fitted where defects were removed
 and extra fastenings placed in cheeks. Fore bressle trees strengthened where
 sprung by an iron plate fitted on side and top.
 Deck pieced at places, where necessary.

Present Condition of the					
Decks	Good	Freemails Botto	Good	Windlass and Capstan	Good
Waterways	Do	Breasthooks and Stemson		Pumps	Do
Comings	Do	Transoms, Pointers, and Crutches		Boats	Do
Upper Deck Beams & Fastenings	Do	Timbers of the Frame at the openings		Masts, Yards, &c.	Do
Lower Deck Beams & Fastenings	Do	Ditto Ditto at other places	where	Condition, how ascertained	From aloft
Planksheers	Do	Keelsons		Sails	Good
Sheerstrakes	Do	Clamps and Shelves		Anchors No. of	33 15 2 K
Topsides	Do	Ceiling	seen	Cables	Good where seen
Wales	Do	Rudder	Good	Hawsers and Warps	Do
Plank (Bottom) and Counter	Do where seen	Copper	Y.M. When put on	Standing & Running Rigging	Good
Engine Room Skylights		Caulking of		Cargo and Main Hatchways	Do
General Observations, Opinion as to Class, &c.		Bottom, Deck, & Waterways	Good	Hatches	Do
		Coal Bunker, Openings, Lids, &c.			
		Scuppers	Do		

She now appears to be in a good and efficient condition
 and is eligible in our opinion to remain as classed

The Amount of Entry Fee ... £ : : : received by me, 24 March 1879
 20/3/79 Special ... £ 1 : 1 :
 Certificate (if required) ... £ : 5 :
 (Travelling Expenses, if any, £)

Committee's Minute

Character assigned

J. Shearley

Thos. Congdon

Surveyor to Lloyd's Register of British and Foreign Shipping.

21st March, 1879

16 TRUF



© 2021

Lloyd's Register
 Foundation

LN0603-0311