

ANNUAL SURVEYS.

37.974

No. 1030 Survey held at London Date, first Survey 20 March 1879 Last Survey 27th March 1879
 No. in on the S. Collingrove (Composite) Master J. Sanderson
 Reg. Book. 1030 Tonnage 861 Built at Sunderland When built 1869 7 mo
 By whom built Laird Owners A. L. Elder &
 Port belonging to London Destined Voyage Melade
 If Surveyed Afloat or in Dry Dock Ratcliffe Dry Dock

Last Survey, No. 36349 Port of London
 Present Condition of the
 Decks Good Treenails Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places where
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling seen
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. When put on 77
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Vessel mended with ballast and part outward cargo in hold - Metal sheathing patched and painted - Inetofunat removed with P. Pail. She is now in a good and efficient condition and eligible in my opinion to remain as classed

Committee's Minute 1st April 1879
 Character assigned 10A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) PAID 18

No. 515 Survey held at London Date, first Survey 25 March 1879 Last Survey 25 March 1879
 No. in on the K. Triumph Master Kent
 Reg. Book. 515 Tonnage 75 Built at Poole When built 1845 9 mo
 By whom built Meadus Owners A. Meadus & Son
 Port belonging to Poole Destined Voyage
 If Surveyed Afloat or in Dry Dock Afloat in River Hamble

Last Survey, No. 1664 Port of Southampton Classed 10
 Present Condition of the
 Decks Good Treenails Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places where
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling seen
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good where seen Copper or Y.M. When put on Good
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. She is now in a good and efficient condition and is eligible in my opinion to remain as classed

Committee's Minute 1st April 1879
 Character assigned 10A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) PAID 18