

# ANNUAL SURVEYS.

38667

Recd 1.5.79

Survey held at London Date, first Survey 5/4/79 Last Survey 10<sup>th</sup> Apr. 1879  
 on the Barque "Montrose" Master L. Allen  
 Tonnage 365 Built at Jersey When built 1861-7 mo  
 By whom built J. B. Gebel Owners Scrutton Sons & Co.  
 Port belonging to London Destined Voyage St Vincent.  
 If Surveyed Afloat or in Dry Dock Union Dry Dock.

Last Survey, No. 26230 Port of Liverpool

Present Condition of the Decks <u>Good</u>	Treenails <u>Good</u>	H. T. Lm. <u>77.</u>	Classed <u>10</u>	Years assigned. <u>10-78.</u>	Character in Register Book. <u>A.1.</u>
Waterways <u>---</u>	Breasthooks and Stemson <u>---</u>	Cash. Lm. <u>72-7 yrs</u>			
Comings <u>---</u>	Transoms, Pointers, and Crutches <u>---</u>	Windlass and Capstan <u>Good</u>			
Upper Deck Beams & Fastenings <u>---</u>	Timbers of the Frame at the Openings <u>where</u>	Pumps <u>---</u>			
Lower Deck Beams & Fastenings <u>---</u>	Ditto ditto at other places <u>seen</u>	Boats <u>---</u>			
Planksheers <u>---</u>	Keelsons <u>---</u>	Masts, Yards, &c. <u>---</u>			
Sheerstrakes <u>---</u>	Clamps and Shelves <u>---</u>	Condition, how ascertained <u>From Deck</u>			
Topsides <u>---</u>	Ceiling <u>---</u>	Sails <u>Good</u>			
Wales <u>---</u>	Rudder <u>---</u>	Anchors, No. of <u>3 1/2 10<sup>th</sup> 2 1/2 age</u>			
Plank (Bottom) and Counter <u>---</u>	Copper or Y.M. <u>on felt</u> When put on <u>1877</u>	Cables <u>Good</u>			
Engine Room Skylights <u>---</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Hawsers and Warps <u>do.</u>			
Coat Buckers, Openings, Lids, &c. <u>---</u>	Scuppers <u>Good</u>	Standing and Running Rigging <u>do.</u>			

General Observations, Opinion as to Class, &c. Bottom sighted and the y. M. patched, added an iron strap on the fore side of knighthead to set up fore stay.  
This vessel is in good and efficient condition and eligible to remain as classed.

Committee's Minute 6th May, 1879.  
 Character assigned Courtesy  
T.B.W.

Thos Wm Blasell  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. in Reg. Book. on the 929 Survey held at London Date, first Survey 23<sup>rd</sup> Apr. Last Survey 23<sup>rd</sup> Apr. 1879  
 on the Brig "Upherooid" Master Plater  
 Tonnage 254 Built at Bermuda When built 1826.  
 By whom built --- Owners Scrutton Sons & Co  
 Port belonging to London Destined Voyage Dominica  
 If Surveyed Afloat or in Dry Dock West India Dock Afloat

Last Survey, No. 36549 Port of London

Present Condition of the Decks <u>Good</u>	Treenails <u>not seen</u>	H. T. Lm. <u>75 6 yrs</u>	Classed <u>9</u>	Years assigned. <u>9-77</u>	Character in Register Book. <u>A.1. Red</u>
Waterways <u>---</u>	Breasthooks and Stemson <u>---</u>	Windlass and Capstan <u>Good</u>			
Comings <u>---</u>	Transoms, Pointers, and Crutches <u>---</u>	Pumps <u>---</u>			
Upper Deck Beams & Fastenings <u>---</u>	Timbers of the Frame at the Openings <u>---</u>	Boats <u>---</u>			
Lower Deck Beams & Fastenings <u>---</u>	Ditto ditto at other places <u>---</u>	Masts, Yards, &c. <u>---</u>			
Planksheers <u>---</u>	Keelsons <u>---</u>	Condition, how ascertained <u>From Deck</u>			
Sheerstrakes <u>---</u>	Clamps and Shelves <u>---</u>	Sails <u>Good</u>			
Topsides <u>---</u>	Ceiling <u>---</u>	Anchors, No. of <u>3 1/2 10- 2k.</u>			
Wales <u>---</u>	Rudder <u>---</u>	Cables <u>Good</u>			
Plank (Bottom) and Counter <u>not seen</u>	Copper or Y.M. <u>---</u> When put on <u>---</u>	Hawsers and Warps <u>do.</u>			
Engine Room Skylights <u>---</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Standing and Running Rigging <u>do.</u>			
Coat Buckers, Openings, Lids, &c. <u>---</u>	Scuppers <u>Good</u>	Cargo and Main Hatchways <u>Good</u>			

General Observations, Opinion as to Class, &c. Surveyed Afloat with the hold full of outward bound cargo, the vessel where seen in good and efficient condition.

Committee's Minute 6th May, 1879.  
 Character assigned Audred  
T.B.W.

Thos Wm Blasell  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18