

ANNUAL SURVEYS.

38163

No. 217 Survey held at London Date, first Survey May 6th Last Survey May 24 18 77
 No. in on the S Renown Master Mildash
 Reg. Book. 217 Tonnage 1253 Built at London When built 1860 5M
 By whom built Green Owners R & H Green
 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 34453 Port of London
 Present Condition of the Decks Good Treenails Good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " ~~Copper or Y.M.~~ 3 Metal When put on 1877
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. She is now in good condition and entitled to remain as classed. The Yellow Metal has now been patched & coated in the present voyage & then will go through the Half Time survey.

Committee's Minute 30th May, 1877 Senhouse Martin
 Character assigned Coups Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. 1198 Survey held at London Date, first Survey May 9th Last Survey May 8th 18 77
 No. in on the BK Constance Master J Mills
 Reg. Book. 1198 Tonnage 367 Built at Newhaven When built 1858
 By whom built London Owners Scrutton Sons & Co
 Port belonging to London Destined Voyage Trinidad
 If Surveyed Afloat or in Dry Dock Pontoon

Last Survey, No. 36449 Port of London
 Present Condition of the Decks Good Treenails Good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " ~~Copper or Y.M.~~ 3 Metal When put on 77
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Yellow Metal Patched

Committee's Minute 30th May, 1877 Senhouse Martin
 Character assigned Coups Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18