

38.221
REPORT of SURVEY for REPAIRS, &c.

No. _____ (Received at London Office, Recd 24.6.79)
No. in Survey held at London Date, first Survey April 12 Last Survey June 21 1879
Reg. Book. _____
443 on the S Windsor Castle Master _____
TONNAGE under Tonnage Deck 960 YEAR. MONTH.
Ditto of Spar Deck, or Avoing Deck _____ Built at Sunderland When built 1857
Ditto of Poop _____ Owners R & B Green Port belonging to London
Ditto of Raised Or. Dk. _____ Residence _____
Ditto of Houses on Deck _____ By whom built _____ Destined Voyage Australia
Ditto of Forecastle _____ If Surveyed Afloat or in Dry Dock Greens Dry Dock
Gross Tonnage 1075
Crew Space, as per Rule _____
Register Tonnage, cut on Beam 1075
Engine Room _____
Reg. Tons as St' mer, cut on Bm. _____
Length of Poop 67 ft. Ditto, Forecastle 33 ft. Ditto, Raised Quarter Deck _____ ft.
Last Survey, No. 34167 Port London Years assigned. Character in Register Book.
REPAIRS, OR EXAMINATION AS PER RULE Classed 14A1-478
Cause of Repairs to be clearly stated. Cont 71-13 Year
HT 76 Bar

At the present time the vessel placed
in dry dock the yellow metal stripped off.
Caulked from keel to load line and Re yellow
Metalled on felt to same height.

Present Condition of the			
Decks	<u>Good</u>	Treenails	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"
Planksheers	"	Keelsons	"
Sheerstrakes	"	Clamps and Shells	"
Topsides	"	Ceiling	"
Wales	"	Rudder	"
Plank (Bottom) and Counter	"	Copper (on Y.M.) <u>By Metal</u> When put on <u>Now</u>	"
Engine Room Skylights	"	Caulking of <u>on felt to load line</u>	"
Coal Bunker, Openings, Lids, &c.	"	Bottom, Deck, & Waterways	<u>Good</u>
General Observations, Opinion as to Class, &c.		Scuppers	<u>Good</u>
		Windlass and Capstan	<u>Good</u>
		Pumps	"
		Boats	"
		Masts, Yards, &c.	"
		Condition, how ascertained	<u>Seen & OK</u>
		Sails	<u>Good</u>
		Anchors No. of <u>3 Bore. 11 & 12 Ridges</u>	"
		Cables <u>Part on OK</u>	<u>Good</u>
		Hawsers and Warps	"
		Standing & Running Rigging	"
		Cargo and Main Hatchways	<u>Good</u>
		Hatches	<u>Good</u>

She is now in good condition
and entitled to remain as classed.

The Amount of Entry Fee ... £ 4 : 7 : 6 received by me,

16/6/79 Special ... £ 2 : 2 : - 30 June 1879

Certificate (if required)
to be sent as per margin... } £ :

(Travelling Expenses, if any, £)

Committee's Minute

Character assigned

27th June, 1879.

Senhouse Martindale
Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register
Foundation

LN663-0415