

REPORT of SURVEY for REPAIRS, &c.

No. 38412

No. in Reg. Book. Survey held at London Date, first Survey 22<sup>nd</sup> August Last Survey, 22<sup>nd</sup> August 1879.

855 on the S. S. "Ludworth" Master Meldrum

TONNAGE under Tonnage Deck 448  
Ditto of Spar Deck, or Avoing Deck  
Ditto of Poop  
Ditto of Raised Qr. Dk.  
Ditto of Houses on Deck  
Ditto of Forecastle  
Gross Tonnage 448  
Crew Space, as per Rule  
Register Tonnage, cut on Beam  
Engine Room  
Reg. Tons as St' mer, cut on Bm. 304

Built at Glasgow When built 1866 5<sup>th</sup>  
Owners Green & Holland Port belonging to London  
Residence  
By whom built Kingate Destined Voyage Antwerp  
If Surveyed Afloat or in Dry Dock Regent's Dry Dock  
Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.  
Last Survey, No. 20554 Port Lrm  
Classed B1  
REPAIRS, OR EXAMINATION AS PER RULE  
S. S. Harpl. No 2-7/8

This vessel was seen by me in dry dock, but a complete examination of bottom has not been made, owing to water being in the dock.  
The Captain was informed that S. S. No 3 is now about due, & a letter to that effect was written to the owners.  
No reply has been received from them & the vessel has been undocked & left for Antwerp.

Present Condition of the  
Decks  
Terways  
Rings  
Deck Beams & Fastenings  
Lower Deck Beams & Fastenings  
Stanchions  
Bulkheads  
Planks  
Floors  
Sides  
Keel (Bottom) and Counter  
Engine Room Skylights  
Coal Bunker, Openings, Lids, &c.  
Scuppers  
Cargo and Main Hatchways  
Hatches  
Treenails  
Breasthooks and Stemson  
Transoms, Pointers, and Crutches  
Timbers of the Frame at the openings  
Ditto Ditto at other places  
Keelsons  
Clamps and Shelves  
Ceiling  
Rudder  
Copper  
When put on  
Caulking of  
Bottom, Deck, & Waterways  
Windlass and Capstan  
Pumps  
Boats  
Masts, Yards, &c.  
Condition, how ascertained  
Sails  
Anchors No. of  
Cables  
Hawsers and Warps  
Standing & Running Rigging

General Observations, Opinion as to Class, &c.  
I beg to leave this case for the consideration of the Committee.

The Amount of Entry Fee ... £ : : received by me, }  
Special ... £ : : 18 }  
Certificate (if required) ... £ : :  
(The expenses, if any, £ )  
Committee's Minute  
Character assigned  
2nd September, 1879  
H. Paulsen  
Surveyor to Lloyd's Register of British and Foreign Shipping.  
Lloyd's Register Foundation  
© 2021