

ANNUAL SURVEYS.

38414
rec'd 1.9.79

No. in Reg. Book. **No. 38414** Survey held at London Date, first Survey July 7th Last Survey Aug 27th 1879
 on the S Shannon Master V Shepode
 Tonnage 1292 Built at London When built 1862 5M
 By whom built Green Owners R & F Green
 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Green & Co

Last Survey, No. 34583 Port of London Classed 1404/1078
 Present Condition of the Decks Good Treenails Good Character in Register Book. Classed 1404/1078
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan Good
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats "
 Planksheers " Keelsons " Masts, Yards, &c. "
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained From 5th
 Topsides " Ceiling " Sails Good
 Wales " Rudder " Anchors, No. of 3 No. 12 & 9 No. 9
 Plank (Bottom) and Counter " ~~Copper or Y.M.~~ Y Metal When put on 1877 Cables Parson & Co Good
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Y Metal Patched & Painted

She is now in good condition and entitled to remain as classed.

Committee's Minute 2nd September, 1879. Senhouse Martindale
 Character assigned 29.79 Court G A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in Reg. Book. on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____
 Caulking of Bottom, Deck, & Waterways _____
 Condition, how ascertained _____
 Sails _____
 Anchors, No. of _____
 Cables _____
 Hawseers and Warps _____
 Standing and Running Rigging _____

Committee's Minute _____ 18____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18____

