

ANNUAL SURVEYS.

No. 38514 Survey held at London Date, first Survey 12th Sept Last Survey 12th Sept 1879
 No. in on the 12 "Agnes" Master R. Jones
 Reg. Book. 262 Tonnage 94 Built at N. Brunswick When built 1845
 By whom built Port belonging to Port Madoc? Owners R. Jones & Co
 If Surveyed Afloat or in Dry Dock Regents Dock & Afloat. Destined Voyage Coasting

Last Survey, No. 1848 Port of Portmadoc Classed 5 Years assigned. 5 Character in Register Book. A.1.
 Present Condition of the
 Decks Good Treenails Good S. S. P. Mast. 78-4 yrs 4 28
 Waterways — Breasthooks and Stemson — Windlass and Capstan Good
 Comings — Transoms, Pointers, and Crutches — Pumps —
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings — Boats —
 Lower Deck Beams & Fastenings — Ditto ditto at other places — Masts, Yards, &c. —
 Planksheers — Keelsons — Condition, how ascertained beef &c.
 Sheerstrakes — Clamps and Shelves — Sails Good
 Topsides — Ceiling — Anchors, No. of 2 B 18. 1K-
 Wales — Rudder — Cables Good
 Plank (Bottom) and Counter — Copper or Y.M. When put on — Hawesers and Warps —
 Standing and Running Rigging —
 General Observations, Opinion as to Class, &c. Surveyed Afloat and where seen in good condition, and in my opinion eligible to remain as Classed.

Committee's Minute 30th September, 1879,

Character assigned A.1.

Thos Wm Blayell
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid — 18 —

No. 3594 Survey held at London Date, first Survey 16th Sept Last Survey 17th Sept 1879
 No. in on the 466 Barge "Seadrift" Master J. Chater
 Reg. Book. 466 Tonnage 357 Built at Sunderland When built 1865-1 mo
 By whom built Naigby Owners J. Shorpe
 Port belonging to N. Shields Destined Voyage Philadelphia
 If Surveyed Afloat or in Dry Dock London Dock Afloat

Last Survey, No. 3594 Port of Bristol Classed 10 Years assigned. 10 Character in Register Book. A.1.
 Present Condition of the
 Decks Good Treenails Good C. S. S. P. Mast. 75-7 yrs 6-78
 Waterways — Breasthooks and Stemson — Windlass and Capstan Good
 Comings — Transoms, Pointers, and Crutches — Pumps —
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings — Boats —
 Lower Deck Beams & Fastenings — Ditto ditto at other places — Masts, Yards, &c. —
 Planksheers — Keelsons Part ballast in Condition, how ascertained from beef
 Sheerstrakes — Clamps and Shelves Halo Sails Good
 Topsides — Ceiling — Anchors, No. of 3 B 18 2K age
 Wales — Rudder — Cables Good
 Plank (Bottom) and Counter — Copper or Y.M. in felt When put on 75 Hawesers and Warps —
 Standing and Running Rigging —
 General Observations, Opinion as to Class, &c. Surveyed Afloat and where seen in good condition, hold nearly covered with ballast and outboard bound cargo. She is in my opinion eligible to remain as Classed. The Owner was informed that the vessel was due for Half Time survey, he states that on her return she will be rematched and placed under survey for H. F.

Committee's Minute 30th September, 1879,

Character assigned Cou 7A

Thos Wm Blayell
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid — 18 —