

ANNUAL SURVEYS.

38550

No. 38550 Survey held at London Date, first Survey 18 Sept 79 Last Survey 23 Sept 1879
No. in on the Sr Agnes Ellen Master B. George
Reg. Book. 276 Tonnage 152 Built at Swansea When built 1875 - 11 mo
By whom built Martin Owners J. Rees & Co
Port belonging to Swansea Destined Voyage St Lucia
If Surveyed Afloat or in Dry Dock Afloat in W. India Sea

Last Survey, No. 23444 Port of Swansea

Classed 11 Years assigned. 12.7.5 Character in Register Book. A 1

Present Condition of the Decks

Waterways	Good	Treenails	Good	Windlass and Capstan	Good
Comings	Good	Breasthooks and Stemson	Good	Pumps	Good
Upper Deck Beams & Fastenings	Good	Transoms, Pointers, and Crutches	Good	Boats	Good
Lower Deck Beams & Fastenings	Good	Timbers of the Frame at the Openings	Good	Masts, Yards, &c.	Good
Planksheers	Good	Ditto ditto at other places	Good	Condition, how ascertained	From deck
Sheerstrakes	Good	Keelsons	Good	Sails	Good
Topsides	Good	Clamps and Shelves	Good	Anchors, No. of	2B. 1S. 1K
Wales	Good	Ceiling	Good	Cables	part seen Good
Plank (Bottom) and Counter	Good	Rudder	Good	Hawsers and Warps	Good
Engine Room Skylights	Good	Copper or Y.M. over J When put on	75	Standing and Running Rigging	Good
Coal Bunker, Openings, Lids, &c.	Good	Caulking of Bottom, Deck, & Waterways	Good	Cargo and Main Hatchways	Good
General Observations, Opinion as to Class, &c.	Good	Scuppers	Good	Hatches	Good

She now appears to be in a good condition and is eligible in my opinion to remain as classed.

Committee's Minute

14th October, 1879.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

No. Survey held at London Date, first Survey 20 Sept 79 Last Survey 9 Oct 1879
No. in on the Sr Chocolate Girl Master Foote
Reg. Book. 722 Tonnage 244 Built at Littlehampton When built 1869 - 8 mo
By whom built Harvey Owners De Patron & Co
Port belonging to London Destined Voyage London Grenada
If Surveyed Afloat or in Dry Dock Afloat in W. India Sea

Last Survey, No. 34037 Port of London

Classed 17 Years assigned. 3.7.8 Character in Register Book. A 1

Present Condition of the Decks

Waterways	Good	Treenails	Good	Windlass and Capstan	Good
Comings	Good	Breasthooks and Stemson	Good	Pumps	Good
Upper Deck Beams & Fastenings	Good	Transoms, Pointers, and Crutches	Good	Boats	Good
Lower Deck Beams & Fastenings	Good	Timbers of the Frame at the Openings	Good	Masts, Yards, &c.	Good
Planksheers	Good	Ditto ditto at other places	Good	Condition, how ascertained	From aloft
Sheerstrakes	Good	Keelsons	Good	Sails	Good
Topsides	Good	Clamps and Shelves	Good	Anchors, No. of	3B. 1S. 2K
Wales	Good	Ceiling	Good	Cables	part seen Good
Plank (Bottom) and Counter	Good	Rudder	Good	Hawsers and Warps	Good
Engine Room Skylights	Good	Copper or Y.M. over J When put on	78	Standing and Running Rigging	Good
Coal Bunkers, Openings, Lids, &c.	Good	Caulking of Bottom, Deck, & Waterways	Good	Cargo and Main Hatchways	Good
General Observations, Opinion as to Class, &c.	Good	Scuppers	Good	Hatches	Good

main boom renewed.
She is now in a good condition and eligible in my opinion to remain as classed.

Committee's Minute

14th October, 1879.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18