

# REPORT of SURVEY for REPAIRS, &c.

No. 38660

(Rec'd 21st 11/79)

No. in Reg. Book. Survey held at London Date, first Survey Nov Last Survey 19th Nov 18 79.

07 Supp. on the B'n "Crossowen" Latet "Omega" Master J. Weeks.

TONNAGE under Tonnage Deck 219  
 Ditto of Spar Deck, or Awning Deck  
 Ditto of Poop  
 Ditto of Raised Qr. Dk.  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage 244  
 Crew Space, as per Rule  
 Register Tonnage, cut on Beam 239  
 Engine Room  
 Reg. Tons as St'mer, cut on Bm.

Built at Grangemouth When built 1878  
 Owners Thos & Cameron Port belonging to Glasgow  
 Residence Glasgow  
 By whom built Adamson Destined Voyage Trinidad  
 If Surveyed Afloat or in Dry Dock Globe Dry Dock &c.

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. 12 Character in Register Book. A.S.

Last Survey, No. 38329 Port London Classed 12 79

REPAIRS, OR EXAMINATION AS PER RULE Stalling &c.  
Bottom lighted, Vessel recaulked  
from keel to gunwale and the bottom sheathed  
with yellow metal over felt.

Cause of Repairs to be clearly stated.

Present Condition of the			
Decks	<u>Good</u>	Treenails	<u>Good</u>
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the openings	<u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto Ditto at other places	<u>"</u>
Planksheers	<u>"</u>	Keelsons	<u>"</u>
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>
Wales	<u>"</u>	Rudder	<u>"</u>
Plank (Bottom) and Counter	<u>"</u>	Copper <u>y. M. F.</u> When put on <u>now</u>	
Engine Room Skylights	<u>"</u>	Caulking of	
Coal Bunker, Openings, Lids, &c.	<u>"</u>	Bottom, Deck, & Waterways	<u>Good</u>
		Scuppers	<u>Good</u>
		Cargo and Main Hatchways	<u>Good</u>
		Hatches	<u>Good</u>
		Windlass and Capstan	<u>Good</u>
		Pumps	<u>"</u>
		Boats	<u>"</u>
		Masts, Yards, &c.	<u>"</u>
		Condition, how ascertained	<u>Deck</u>
		Sails	<u>Good</u>
		Anchors No. of <u>3 B- 1 B- 1 H.</u>	
		Cables	<u>Good</u>
		Hawsers and Warps	<u>do</u>
		Standing & Running Rigging	<u>do</u>

General Observations, Opinion as to Class, &c. This Vessel is now in good and  
efficient condition, and eligible to remain as  
Classed.

The Amount of Entry Fee ... £ 1 : 1 : 0 received by me, Thos Wm Blayell  
 Special ... £ 1 : 1 : 0 16th Nov 1879  
 Certificate (if required) ... £ 5 : 0 : 0  
 (Travelling Expenses, if any, £ )

Committee's Minute 25th November, 1879.

Character assigned 12 A

Thos Wm Blayell  
 Surveyor to Lloyd's Register of British and Foreign Shipping.

[1,000—28,978.]