

## ANNUAL SURVEYS.

No. 38677 Survey held at London Date, first Survey Aug. 26 Last Survey Aug. 26 1877  
 No. in on the B.M. "Electra" Master Taylor  
 Reg. Book. 301 Tonnage 225 Built at P. C. Island When built 1869 - 7 mo.  
 By whom built M. C. Longall Owners C. W. & W. Gray  
 Port belonging to Liverpool Destined Voyage St. Vincent.  
 If Surveyed Afloat or in Dry Dock Union Dry Dock.

Last Survey, No. 36601 Port of London

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Classed	<u>8 A.1.</u>
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Years assigned.	<u>10-77.</u>
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Character in Register Book.	
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the Openings	<u>"</u>		
Lower Deck Beams & Fastenings	<u>"</u>	Ditto ditto at other places	<u>"</u>		
Planksheers	<u>"</u>	Keelsons	<u>Ballast</u>		
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>in</u>		
Topsides	<u>"</u>	Ceiling	<u>half</u>		
Wales	<u>"</u>	Rudder	<u>Good</u>		
Plank (Bottom) and Counter	<u>"</u>	Copper or Y.M. in felt When put on <u>1877</u>			
Engine Room Skylights	<u>✓</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>		
Coal Bunkers, Openings, Lids, &c.	<u>✓</u>	Scuppers	<u>Good</u>		
General Observations, Opinion as to Class, &c.	<u>Bottom sighted and the yellow metal sheathing patched.</u>				
	<u>This Vessel is now in good and efficient condition, and eligible to remain as Classed.</u>				

Committee's Minute 23rd November 18 77.

Character assigned Class 5A

Thos Wm Blayell.  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. 57 Survey held at London Date, first Survey 18th Nov 1870.  
 No. in on the B. Gate Bousfield Master Williams  
 Reg. Book. 57 Tonnage 274 Built at Belfast When built 1876 - 1 mo.  
 By whom built M. Laine Owners J. Fisher &  
 Port belonging to Barrow Destined Voyage South America  
 If Surveyed Afloat or in Dry Dock Wapping Basin.

Last Survey, No. 2356 Port of Belfast

Present Condition of the				Classed	<u>10</u>	<u>A.1.</u>
Decks	<u>Good</u>	Treenails	<u>Good</u>	Years assigned.	<u>10</u>	<u>1876</u>
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Character in Register Book.		
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>			
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the Openings	<u>"</u>			
Lower Deck Beams & Fastenings	<u>"</u>	Ditto ditto at other places	<u>"</u>			
Planksheers	<u>"</u>	Keelsons	<u>"</u>			
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>			
Topsides	<u>"</u>	Ceiling	<u>"</u>			
Wales	<u>"</u>	Rudder	<u>"</u>			
Plank (Bottom) and Counter	<u>not seen</u>	Copper or Y.M. in felt When put on <u>76</u>				
Engine Room Skylights	<u>✓</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>			
Coal Bunkers, Openings, Lids, &c.	<u>✓</u>	Scuppers	<u>Good</u>			
General Observations, Opinion as to Class, &c.	<u>Surveyed afloat and where seen in good condition, and eligible in my opinion to remain as Classed.</u>					

Committee's Minute 28th November 1877.

Character assigned 10A

J. W. Blayell  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18