

ANNUAL SURVEYS. 38429

(Received at London Office, Rec'd 16th 12 79)

No. 28429 Survey held at London Date, first Survey 27th Nov Last Survey Nov 1879
 No. in on the B's "Panda" Master Edwards
 Reg. Book. 71 Tonnage 328 Built at Denmark When built 1874 - 10 mo
 By whom built Wang Owners Bullard King & Co.
 Port belonging to London Destined Voyage Port Natal
 If Surveyed Afloat or in Dry Dock Fountain Dry Dock
 Last Survey, No. 117 Port of Mauritius Classed 12 Years assigned. 10.78 Character in Register Book. A.1.

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Pumps	<u>"</u>
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Boats	<u>"</u>
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the Openings	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto ditto at other places	<u>"</u>	Condition, how ascertained	<u>Deck &c.</u>
Planksheers	<u>"</u>	Keelsons	<u>"</u>	Sails	<u>Good</u>
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>	Anchors, No. of	<u>3 B - 1 S - 2 K.</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>	Cables	<u>Good</u>
Wales	<u>"</u>	Rudder	<u>"</u>	Hawsers and Warps	<u>do</u>
Plank (Bottom) and Counter	<u>"</u>	Copper or Y.M. on felt When put on	<u>"</u>	Standing and Running Rigging	<u>do</u>
Engine Room Skylights	<u>"</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>		
Coal Bunkers, Openings, Lids, &c.	<u>"</u>	Scuppers	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
				Hatches	<u>Good</u>

General Observations, Opinion as to Class, &c. Bottom sighted metal patched, and the vessel where seen found in good condition and eligible to remain as classed.

Committee's Minute 19th December, 1879.

Character assigned 12 A

T. W. Blayell.
Thos. Langdon

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 5740 Survey held at London Date, first Survey 24th Nov Last Survey 10th Dec 1879
 No. in on the S'R "Blue Bell" Master L. Guthrie
 Reg. Book. 5740 Tonnage 76 Built at Fraserburgh When built 1873 - 9 mo
 By whom built Webster Owners L. McDonald
 Port belonging to Fraserburgh Destined Voyage Fraserburgh
 If Surveyed Afloat or in Dry Dock Afloat Tower Pier.
 Last Survey, No. 14656 Port of Sunderland Classed 9 Years assigned. A.1.5.77 Character in Register Book. H. Feb 77

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>"</u>	Breasthooks and Stemson	<u>"</u>	Pumps	<u>"</u>
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Boats	<u>"</u>
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the Openings	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto ditto at other places	<u>"</u>	Condition, how ascertained	<u>Deck &c.</u>
Planksheers	<u>"</u>	Keelsons	<u>"</u>	Sails	<u>Good</u>
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>	Anchors, No. of	<u>2 B - 1 S - 1 K.</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>	Cables	<u>Good</u>
Wales	<u>"</u>	Rudder	<u>"</u>	Hawsers and Warps	<u>do</u>
Plank (Bottom) and Counter	<u>not seen</u>	Copper or Y.M. When put on	<u>"</u>	Standing and Running Rigging	<u>do</u>
Engine Room Skylights	<u>"</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>		
Coal Bunkers, Openings, Lids, &c.	<u>"</u>	Scuppers	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
				Hatches	<u>Good</u>

General Observations, Opinion as to Class, &c. Surveyed afloat and seen found in good condition, and in my opinion eligible to remain as classed

Committee's Minute 19th December, 1879.

Character assigned 9 A

T. W. Blayell.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18