

ANNUAL SURVEYS.

39006

No. 39006 Survey held at London Date, first Survey 5th March Last Survey 5th March 18 80
 No. in on the Reg. Book. 365 Tonnage 261 Built at Perrey Master B. Bennett
 By whom built 573 Owners Scrutton & Sons
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 34612 Port of Lon

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Years assigned.	<u>12</u>	Character in Register Book	<u>At Red 78</u>
Waterways	<u>de</u>	Breasthooks and Stemson	<u>de</u>	<u>08</u>	<u>12</u>	<u>At Red 78</u>	<u>12</u>
Comings	<u>de</u>	Transoms, Pointers, and Crutches	<u>de</u>				
Upper Deck Beams & Fastenings	<u>de</u>	Timbers of the Frame at the Openings	<u>de</u>				
Lower Deck Beams & Fastenings	<u>de</u>	Ditto ditto at other places	<u>de</u>				
Planksheers	<u>de</u>	Keelsons	<u>de</u>				
Sheerstrakes	<u>de</u>	Clamps and Shelves	<u>de</u>				
Topsides	<u>de</u>	Ceiling	<u>de</u>				
Wales	<u>de</u>	Rudder	<u>de</u>				
Plank (Bottom) and Counter	<u>de</u>	Copper or Y.M. <u>Y.M.</u> When put on <u>78</u>	<u>de</u>				
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	<u>de</u>				
Coal Bunker, Openings, Lids, &c.		Scuppers	<u>de</u>				
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	<u>de</u>				
		Hatches	<u>de</u>				

This Vessel appears in good condition and eligible to remain as classed.

Surveyed with outward cargo in midship hold and dunnage at the ends

Committee's Minute Thursday, March, 25th 1880

Character assigned

At Red 78
T.B.W.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. 39007 Survey held at London Date, first Survey 17 March Last Survey 17 March 18 80
 No. in on the Reg. Book. 362 Tonnage 561 Built at Liverpool Master Peable
 By whom built Austen Owners Hankin & Co
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock

Last Survey, No. 34498 Port of London

Present Condition of the		Treenails	<u>Good</u>	Years assigned.	<u>14</u>	Character in Register Book	<u>At 9. 78</u>
Decks	<u>Good</u>	Breasthooks and Stemson	<u>de</u>	<u>14</u>	<u>14</u>	<u>At 9. 78</u>	<u>14</u>
Waterways	<u>de</u>	Transoms, Pointers, and Crutches	<u>de</u>				
Comings	<u>de</u>	Timbers of the Frame at the Openings	<u>de</u>				
Upper Deck Beams & Fastenings	<u>de</u>	Ditto ditto at other places	<u>de</u>				
Lower Deck Beams & Fastenings	<u>de</u>	Keelsons	<u>de</u>				
Planksheers	<u>de</u>	Clamps and Shelves	<u>de</u>				
Sheerstrakes	<u>de</u>	Ceiling	<u>de</u>				
Topsides	<u>de</u>	Rudder	<u>de</u>				
Wales	<u>de</u>	Copper or Y.M. <u>Y.M.</u> When put on <u>78</u>	<u>de</u>				
Plank (Bottom) and Counter	<u>de</u>	Caulking of Bottom, Deck, & Waterways	<u>de</u>				
Engine Room Skylights		Scuppers	<u>de</u>				
Coal Bunkers, Openings, Lids, &c.		Cargo and Main Hatchways	<u>de</u>				
General Observations, Opinion as to Class, &c.		Hatches	<u>de</u>				

This Vessel appears in good condition and eligible to remain as classed.

Surveyed with ballast in midship hold and dunnage at ends

Committee's Minute Thursday, March, 25th 1880

Character assigned

At 9. 78
T.B.W.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

Roseau

12

