

ANNUAL SURVEYS. 39204

No. 39204 Survey held at London Date, first Survey 22 April Last Survey 13 May 1880
No. in on the Latona Master Latham
Reg. Book. 231 Tonnage 693 Built at Sunderland When built 1857
By whom built 408 Owners J. H. Allan
Port belonging to London Destined Voyage Madras
If Surveyed Afloat or in Dry Dock Lincolns dry dock

Last Survey, No. 1980 Port of Gal
Present Condition of the
Decks Good Treenails Good
Waterways do Breasthooks and Stemson do
Comings do Transoms, Pointers, and Crutches do
Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
Lower Deck Beams & Fastenings do Ditto ditto at other places do
Planksheers do Keelsons do
Sheerstrakes do Clamps and Shelves do
Topsides do Ceiling do
Wales do Rudder do
Plank (Bottom) and Counter do Copper or Y.M. Y. M. When put on 79
Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers do Cargo and Main Hatchways do
General Observations, Opinion as to Class, &c. Hatches do

Yellow Metal repaired. This vessel appears eligible to remain as classed.

Committee's Minute

Tuesday, May, 15th 1880.

Character assigned

Class G.A.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) 5/ Paid 24/5/ 1880

No. Survey held at London Date, first Survey 5 May Last Survey 8 May 1880
No. in on the Bth "Mayola" Master W. H. Ray
Reg. Book. 875 Tonnage 334 Built at Belfast When built 1856
By whom built 7 Owners J. F. Quinn
Port belonging to London Destined Voyage Africa
If Surveyed Afloat or in Dry Dock Afloat W. I. Dock

Last Survey, No. 34168 Port of London
Present Condition of the
Decks Good Treenails Good
Waterways do Breasthooks and Stemson do
Comings do Transoms, Pointers, and Crutches do
Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
Lower Deck Beams & Fastenings do Ditto ditto at other places do
Planksheers do Keelsons do
Sheerstrakes do Clamps and Shelves do
Topsides do Ceiling do
Wales do Rudder do
Plank (Bottom) and Counter do Copper or Y.M. Y. M. When put on 78
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers do Cargo and Main Hatchways do
General Observations, Opinion as to Class, &c. Hatches do

This vessel appears in good condition and eligible to remain as classed.

Committee's Minute

Tuesday, May, 18th 1880.

Character assigned

Class G.A.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

