

## ANNUAL SURVEYS.

(Received at London Office)

No. 39344 Survey held at London Date, first Survey 27 May Last Survey 29 June 1880  
No. in on the Barque "Glen Osmond" Master Maples  
Reg. Book. 413 Tonnage 780 Built at Sunderland When built 1867-8  
By whom built Laird Owners A. L. Elder  
Port belonging to London Destined Voyage A. Glendale  
If Surveyed Afloat or in Dry Dock Ritchie dry dock  
Last Survey, No. 38243 Port of London Classed 18 A1 6.79

Present Condition of the  
Decks Good Treenails Good Bolts Good  
Waterways dc Breasthooks and Stemson dc  
Comings dc Transoms, Pointers, and Crutches dc  
Upper Deck Beams & Fastenings dc Timbers of the Frame at the Openings dc  
Lower Deck Beams & Fastenings dc Ditto ditto at other places dc  
Planksheers dc Keelsons dc  
Sheerstrakes dc Clamps and Shelves dc  
Topsides dc Ceiling dc  
Wales dc Rudder dc  
Plank (Bottom) and Counter dc Copper or Y.M. dc When put on 78  
Engine Room Skylights dc Caulking of dc  
Coal Bunker, Openings, Lids, &c. dc Bottom, Deck, & Waterways dc  
Scuppers dc Cargo and Main Hatchways dc  
Hatches dc  
Windlass and Capstan Good  
Pumps two dc  
Boats four dc  
Masts, Yards, &c. dc  
Condition, how ascertained from deck  
Sails well found  
Anchors, No. of 3 B. 1 S. & Keages  
Cables complete  
Hawsers and Warps sufficient  
Standing and Running Rigging good

General Observations, Opinion as to Class, &amp;c.

*This vessel appears in good condition and eligible to remain as classed.*  
*Engine and fore top gallant yards new.*

Committee's Minute

Friday, July, 2nd 18 80

Character assigned

18A1

Thos. Bougdon

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No. Survey held at London Date, first Survey 15 Jan Last Survey 27 June 1880  
No. in on the 3 Mast "Mittie Bain" Master S. Lock  
Reg. Book. 1082 Tonnage 232 Built at Hayle When built 1872-3  
By whom built Harvey Owners Bain & Co  
Port belonging to Hayle Destined Voyage Demerara  
If Surveyed Afloat or in Dry Dock afloat N. S. Dock

Last Survey, No. PhyPort of 2956Classed 12

Years assigned.

Character in Register Book.

A1 7.77H.T. 77

Present Condition of the  
Decks Good Treenails Good  
Waterways dc Breasthooks and Stemson dc  
Comings dc Transoms, Pointers, and Crutches dc  
Upper Deck Beams & Fastenings dc Timbers of the Frame at the Openings dc  
Lower Deck Beams & Fastenings dc Ditto ditto at other places dc  
Planksheers dc Keelsons dc  
Sheerstrakes dc Clamps and Shelves dc  
Topsides dc Ceiling dc  
Wales dc Rudder dc  
Plank (Bottom) and Counter dc Copper or Y.M. Y.M. When put on 77  
Engine Room Skylights dc Caulking of dc  
Coal Bunkers, Openings, Lids, &c. dc Bottom, Deck, & Waterways dc  
Scuppers dc Cargo and Main Hatchways dc  
Hatches dc  
Windlass and Capstan Good  
Pumps two dc  
Boats two dc  
Masts, Yards, &c. dc  
Condition, how ascertained from deck  
Sails well found  
Anchors, No. of 3 B. 1 S. & Keages  
Cables complete  
Hawsers and Warps sufficient  
Standing and Running Rigging good

General Observations, Opinion as to Class, &amp;c.

*This vessel appears eligible to remain as classed.*

Committee's Minute

Friday, July, 2nd 18 80

Character assigned

12A1

Thos. Bougdon

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

LON 664-0342



Her Asmons



© 2021

Lloyd's Register  
Foundation

ВНИМАТЕЛЬНО ПРОЧИТАЙТЕ