

ANNUAL SURVEYS.

(Received at London Office, 77 80)

39373

No. 2927 Survey held at London Date, first Survey 19th June Last Survey 6th July 1880
 No. in on the Bkn. "Satellite" Master J. Hunter
 Reg. Book. 321 Tonnage 275 275 286 Built at Garmouth When built 1867 5mo
 By whom built Geddie Owners C. H. & H. Gray
 Port belonging to London Destined Voyage Trinidad
 If Surveyed Afloat X in Dry Dock Union Dry Dock

Last Survey, No. 38712 Port of Lon Classed 9 A1
 Years assigned. 7 Character in Register Book. 12.79
 Present Condition of the Decks Good Treenails Good Con Lon. May '6
 Waterways do Breasthooks and Stemson do Windlass and Capstan Good
 Comings do Transoms, Pointers, and Crutches do Pumps do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Boats do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do Masts, Yards, &c. do
 Planksheers do Keelsons do Condition, how ascertained from deck & enquiry
 Sheerstrakes do Clamps and Shelves do Sails do
 Topsides do Ceiling do Anchors, No. of 3 B. 1 St. 2 H.
 Wales do Rudder do Cables part seen
 Plank (Bottom) and Counter do Copper or Y.M. on felt When put on 1877 Hawseers and Warps do
 Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers do Cargo and Main Hatchways good Hatches do
 General Observations, Opinion as to Class, &c. —

Bottom sighted; metal sheathing patched. -
Supplied a stream anchor 4. 6. 16, test 6. 12. 2. 0, number of cert. 8967, dated Newcastle 28th Jan. 1880, signed D. L. Lewis
acquainted owners representative that the Half Yearly survey is nearly due; owner desires to postpone this survey.

She is in good condition & eligible in my opinion to remain as classed -
 Committee's Minute Friday July 9th 18 80 W. Paulsen.
 Character assigned Cert A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid — 18—

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
 Years assigned. _____ Character in Register Book. _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____ Windlass and Capstan _____
 Comings _____ Transoms, Pointers, and Crutches _____ Pumps _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ Boats _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ Masts, Yards, &c. _____
 Planksheers _____ Keelsons _____ Condition, how ascertained _____
 Sheerstrakes _____ Clamps and Shelves _____ Sails _____
 Topsides _____ Ceiling _____ Anchors, No. of _____
 Wales _____ Rudder _____ Cables _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____ Hawseers and Warps _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18____

