

# ANNUAL SURVEYS.

(Received at London Office, 7.7.80)

No. 39374 Survey held at London Date, first Survey 28th June Last Survey 1st July 18 80  
 No. in on the BR. "Loteria" Master H. E. Jarvis  
 Reg. Book. 857 Tonnage 598 622 551 Built at Falmouth When built 1875 4th mo  
 By whom built Voethovan Owners Balkwill & Co.  
 Port belonging to Salcombe Destined Voyage Rangoon  
 If Surveyed Afloat or in Dry Dock West India Graving Dock

Last Survey, No. 38432 Port of Lon Classified 13 A1  
 Years assigned. 9.79 Character in Register Book.

Present Condition of the  
 Decks Good Treenails Good  
 Waterways do Breasthooks and Stemson do  
 Comings do Transoms, Pointers, and Crutches do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do  
 Planksheers do Keelsons do  
 Sheerstrakes do Clamps and Shelves do  
 Topsides do Ceiling do  
 Wales do Rudder do  
 Plank (Bottom) and Counter do Copper or Y.M. on felt When put on 1879  
 Engine Room Skylights do Caulking of Bottom, Deck, & Waterways good  
 Coal Bunker, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways good Hatches do  
 General Observations, Opinion as to Class, &c.

Bottom sighted; metal sheathing patched.  
Exam'd where practicable & found good.

She is in good condition & eligible in my opinion to remain as classed.

Committee's Minute Friday, July, 9th 18 80 H. Paulsen.  
 Character assigned 13 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) DTM Paid 18

No. 39374 Survey held at London Date, first Survey 5th July Last Survey 5th July 18 80  
 No. in on the Ship "Parramatta" Master Goddard  
 Reg. Book. 132 Tonnage 1521 1521 1298 Built at Sunderland When built 1866 5th mo  
 By whom built Laing Owners Devitt & Moore  
 Port belonging to London Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock West India Graving Dock

Last Survey, No. 38357 Port of Lon Classified 16 A1  
 Years assigned. 7.79 Character in Register Book.

Present Condition of the  
 Decks Good Treenails Good  
 Waterways do Breasthooks and Stemson do  
 Comings do Transoms, Pointers, and Crutches do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do  
 Planksheers do Keelsons do  
 Sheerstrakes do Clamps and Shelves do  
 Topsides do Ceiling do  
 Wales do Rudder do  
 Plank (Bottom) and Counter do Copper or Y.M. on felt When put on 1878  
 Engine Room Skylights do Caulking of Bottom, Deck, & Waterways good  
 Coal Bunkers, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways good Hatches do  
 General Observations, Opinion as to Class, &c.

Bottom sighted; metal sheathing patched & painted.  
Surveyed with ballast in hold all fore & aft.

She is in good condition & eligible in my opinion to remain as classed.

Committee's Minute Friday, July, 9th 18 80 H. Paulsen.  
 Character assigned 16 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) DTM Paid 18



Loteria  
Parramatta

ANNUAL SURVEYS

