

ANNUAL SURVEYS.

394

(Received at London Office, 16. 7. 80)

No. 3945 Survey held at London Date, first Survey 2 July Last Survey 2 July 1880
 No. in Reg. Book. 117 on the Barque "Liba" Master Perry
 Tonnage 573 Built at Aberdeen When built 1858
 By whom built _____ Owners Whitehead & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Limekiln dry dock

Last Survey, No. 38554 Port of London Classed 14 Years assigned 10. 79
26. 76 Character in Register-Book Cont 72-9

Present Condition of the Decks		Treenails	Good	Years assigned	Character in Register-Book
Waterways	<u>de</u>	Breasthooks and Stemson	<u>de</u>		
Comings	<u>de</u>	Transoms, Pointers, and Crutches	<u>de</u>		
Upper Deck Beams & Fastenings	<u>de</u>	Timbers of the Frame at the Openings	<u>de</u>		
Lower Deck Beams & Fastenings	<u>de</u>	Ditto ditto at other places	<u>de</u>		
Planksheers	<u>de</u>	Keelsons	<u>de</u>		
Sheerstrakes	<u>de</u>	Clamps and Shelves	<u>de</u>		
Topsides	<u>de</u>	Ceiling	<u>de</u>		
Wales	<u>de</u>	Rudder	<u>de</u>		
Plank (Bottom) and Counter	<u>de</u>	Copper or Y.M. <u>Y.M.</u> When put on <u>179</u>			
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	<u>de</u>		
Coal Bunker, Openings, Lids, &c.		Scuppers	<u>de</u>		
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	<u>de</u>		
		Hatches	<u>de</u>		

This vessel appears eligible to remain as classed.

Surveyed with ballast in the main hold

Committee's Minute Tuesday, July 20th 1880. Thos Longdon
 Character assigned Cont 9 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at London Date, first Survey 10 July Last Survey 6 July 1880
 No. in Reg. Book. 6 on the 3 Mast Schooner "C.E. Spooner" Master Jones
 Tonnage 186 Built at Portsmouth When built 1878. 8
 By whom built Jones Owners Jones & Co
 Port belonging to Barnarvon Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. 4565 Port of Greenock Classed 12 Years assigned 11. 79
11. 79 Character in Register-Book At

Present Condition of the Decks		Treenails	Good	Years assigned	Character in Register-Book
Waterways	<u>de</u>	Breasthooks and Stemson	<u>de</u>		
Comings	<u>de</u>	Transoms, Pointers, and Crutches	<u>de</u>		
Upper Deck Beams & Fastenings	<u>de</u>	Timbers of the Frame at the Openings	<u>de</u>		
Lower Deck Beams & Fastenings	<u>de</u>	Ditto ditto at other places	<u>de</u>		
Planksheers	<u>de</u>	Keelsons	<u>de</u>		
Sheerstrakes	<u>de</u>	Clamps and Shelves	<u>de</u>		
Topsides	<u>de</u>	Ceiling	<u>de</u>		
Wales	<u>de</u>	Rudder	<u>de</u>		
Plank (Bottom) and Counter	<u>de</u>	Copper or Y.M. _____ When put on _____			
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	<u>de</u>		
Coal Bunkers, Openings, Lids, &c.		Scuppers	<u>de</u>		
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	<u>de</u>		
		Hatches	<u>de</u>		

This vessel appears eligible to remain as classed.

Surveyed with damage over the hold

Committee's Minute Tuesday, July 20th 1880. Thos Longdon
 Character assigned 12 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

Liba

C. E. Spooner

Committee & Minutes



© 2021

Lloyd's Register Foundation

Ллойдс Реджистър