

# ANNUAL SURVEYS.

No. 391490 Survey held at London Date, first Survey 26<sup>th</sup> July Last Survey 26<sup>th</sup> July 1880  
 No. in on the Reg. Book. 249 Tonnage 543 Built at Sunderland Master G. Bush  
 By whom built 511 Overall Owners J. Wilson  
 Port belonging to London Destined Voyage Swan River N. Australia  
 If Surveyed Afloat or in Dry Dock Commercial dry Dock

Last Survey, No. 38246 Port of Trow Classed 16 A1  
 Present Condition of the  
 Decks Good Treenails Bolts & Rivets Good Cont-Lon-49-11 6-49  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan Good  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats "  
 Planksheers " Keelsons " Masts, Yards, &c. "  
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained from the deck  
 Topsides " Ceiling " Sails Complete  
 Wales " Rudder " Anchors, No. of 3 B. 18 & 2 K  
 Plank (Bottom) and Counter " Copper or Y.M. Y. M When put on 1849 Cables Complete  
 Engine Room Skylights " Caulking of " Hawser and Warps 8"  
 General Observations, Opinion as to Class, &c. Bottom, Deck, & Waterways good Standing and Running Rigging "  
Coal Bunker, Openings, Lids, &c. " Scuppers good Cargo and Main Hatchways good Hatches "

Bottom sighted and yellow metal sheathing patched.  
This vessel is now in good condition and in my opinion eligible to remain as classed.

Committee's Minute Friday, August 13<sup>th</sup>, 1880  
 Character assigned Cout 11 MA R. Williamson  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) " Paid 18

No. 974 Survey held at London Date, first Survey 4<sup>th</sup> Aug Last Survey 4<sup>th</sup> Aug 1880  
 No. in on the Reg. Book. 453 Tonnage 480 Built at Dundee Master Harris  
 By whom built 4543 Lay Shipbuilding Co. Owners R. Jolly & Co.  
 Port belonging to London Destined Voyage Mauritius  
 If Surveyed Afloat or in Dry Dock Gun dry Dock

Last Survey, No. 38008 Port of London Classed 11 A1  
 Present Condition of the  
 Decks Good Treenails Good Cont-Lon-Aug 44 7 4-49  
 Waterways " Breasthooks and Stemson " H.T. Lon 49  
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan Good  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats "  
 Planksheers " Keelsons " Masts, Yards, &c. "  
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained from the deck  
 Topsides " Ceiling " Sails Complete  
 Wales " Rudder " Anchors, No. of 3 B. 18 & 2 K  
 Plank (Bottom) and Counter " Copper or Y.M. Y. M When put on " Cables Complete  
 Engine Room Skylights " Caulking of " Hawser and Warps 8"  
 General Observations, Opinion as to Class, &c. Bottom, Deck, & Waterways good Standing and Running Rigging "  
Coal Bunkers, Openings, Lids, &c. " Scuppers good Cargo and Main Hatchways good Hatches "

Bottom sighted and yellow metal sheathing patched.  
This vessel is now in good condition and in my opinion eligible to remain as classed.

Committee's Minute Friday, August 13<sup>th</sup>, 1880  
 Character assigned Cout 7 MA R. Williamson  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) " Paid 18