

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office, 4. 1. 86)

3954  
Survey held at London Date, first Survey 10. Dec. Last Survey 15. Dec. 1880  
on the B.P. Dragon Master C. Horton  
NAME under Tonnage Deck 655  
of Spar Deck, or Awning Deck  
of Poop  
of Raised Qr. Dk.  
of Houses on Deck  
of Forecastle  
ss Tonnage 696  
Space, as per Rule 696  
ster Tonnage, cut on Beam  
ine Room  
Tons as St'mer, cut on Bm.  
h of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.  
t Survey, No. 2527 Port Ingn S.C. Lon. No 3. 76  
AIRS, OR EXAMINATION AS PER RULE  
Cause of Repairs to be clearly stated.

This vessel has been examined in Dry Dock. The bottom cleaned & coated; the Rudder lifted & pintles bushed. The timber boards & ceiling equal to four strakes. All five aft have been removed; the windlass has been unhooked, tripped, and examined; cables ranged and masts & spars examined aloft. The spanker boom has had an iron band fitted round the goose neck. 1 Bulwark Stanchion has been renewed and 4 re-riveted on the Port side and 6 re-riveted on Starb'd side. And a piece of main rail renewed about 20 ft. Fore side of main rigging.

Present Condition of the	Good	Treenails	Stumps	Good	Windlass and Capstan	Good
Decks	- "	Breasthooks and Stenson	- "	- "	Pumps	Complete & "
Waterways	- "	Transoms, Pointers, and Crutches	- "	- "	Boats	" "
Comings	- "	Timbers of the Frame at the openings	- "	- "	Masts, Yards, &c.	" "
Upper Deck Beams & Fastenings	- "	Ditto Ditto at other places	- "	- "	Condition, how ascertained	Exam'd aloft
Lower Deck Beams & Fastenings	- "	Keelsons	- "	- "	Sails	2 suits & Good
Planksheers	- "	Clamps and Shelves	- "	- "	Anchors	No. of 3 B. 1 S. 2 M.
Sheerstrakes	Plating - "	Ceiling	- "	- "	Cables	Complete & Good
Topsides	- "	Rudder lifted & pintles bushed	- "	- "	Hawsers and Warps	" "
Wales	- "	Copper (or Y.M.) Coating When put on	- "	- "	Standing & Running Rigging	" "
Plank (Bottom) and Counter	- "	Caulking of Bottom, Deck, & Waterways	- "	Good	Cargo and Main Hatchways	Good Hatches - "
Engine Room Skylights	- "	Coal Bunker, Openings, Lids, &c.	- "	- "		
General Observations, Opinion as to Class, &c.		Scuppers	- "	- "		

She has complied with the rules, is in good and efficient condition, and eligible, in our opinion, to continue as classed, and to be marked in the Register. -  
S.C. Lon. No 1. 80

The Amount of Entry Fee ... £ " : " : " received by me, }  
4/1/81 Special ... £ 4 : 4 : 0 4/1/81 }  
Certificate (if required) } £ : 5 :  
to be sent as per margin... }  
(Travelling Expenses, if any, £ )  
Committee's Minute Tuesday January, 4th 1881.  
Character assigned

James Turpin  
Willm. C. Davney  
Surveyor to Lloyd's Register of British and Foreign Shipping.  
LLOYD'S REGISTER  
© 2021  
Lloyd's Register Foundation  
LON664-0568